

1 7 1 18 18


INTERIOR EXTERIOR

WINDOW TYPE **9**

EXISTING GLAZING INVENTORY LEGEND
H= HISTORIC SUITABLE FOR REUSE
B= BROKEN UNSUITABLE FOR REUSE
IN THIS LOCATION (SEE GENERAL NOTES)

NOTES
1. EXISTING HARDWARE COMPONENTS ARE IN GOOD TO FAIR SHAPE.
2. SILL IN POOR CONDITION. GAP AT SILL NEEDS TO BE FILLED IN AND SEALED.

1 WINDOW NO. 003A
ROOM 003



1 18 1 18 18


INTERIOR EXTERIOR

WINDOW TYPE **11**

EXISTING GLAZING INVENTORY LEGEND
H= HISTORIC SUITABLE FOR REUSE
B= BROKEN UNSUITABLE FOR REUSE
IN THIS LOCATION (SEE GENERAL NOTES)

NOTES
1. EXISTING WOOD WINDOW FRAME, SILL, HARDWARE, ETC. COMPONENTS ARE IN GOOD TO FAIR CONDITION AND GENERALLY SUITED FOR RESTORATION AND REUSE UNLESS NOTED OTHERWISE.
2. MAKE SURE THERE ARE NO OPENINGS AT SILL, HEAD AND JAMBS.

2 WINDOW NO. 005A
ROOM 005



1 18 1 18 18


INTERIOR EXTERIOR

WINDOW TYPE **11**

EXISTING GLAZING INVENTORY LEGEND
H= HISTORIC SUITABLE FOR REUSE
B= BROKEN UNSUITABLE FOR REUSE
IN THIS LOCATION (SEE GENERAL NOTES)

NOTES
1. EXISTING WOOD WINDOW FRAME, SILL, HARDWARE, ETC. COMPONENTS ARE IN GOOD TO FAIR CONDITION AND GENERALLY SUITED FOR RESTORATION AND REUSE UNLESS NOTED OTHERWISE.

3 WINDOW NO. 005B
ROOM 005



1 18 1 18 18


INTERIOR EXTERIOR

WINDOW TYPE **11**

EXISTING GLAZING INVENTORY LEGEND
H= HISTORIC SUITABLE FOR REUSE
B= BROKEN UNSUITABLE FOR REUSE
IN THIS LOCATION (SEE GENERAL NOTES)

NOTES
1. EXISTING WOOD WINDOW FRAME, SILL, HARDWARE, ETC. COMPONENTS ARE IN GOOD TO FAIR CONDITION AND GENERALLY SUITED FOR RESTORATION AND REUSE UNLESS NOTED OTHERWISE.

4 WINDOW NO. 005C
ROOM 005



1 16 1 16 16

INTERIOR EXTERIOR

WINDOW TYPE **13**


EXISTING GLAZING INVENTORY LEGEND
H= HISTORIC SUITABLE FOR REUSE
B= BROKEN UNSUITABLE FOR REUSE
IN THIS LOCATION (SEE GENERAL NOTES)

NOTES
1. EXISTING WOOD WINDOW FRAME, SILL, HARDWARE, ETC. COMPONENTS ARE IN GOOD TO FAIR CONDITION AND GENERALLY SUITED FOR RESTORATION AND REUSE UNLESS NOTED OTHERWISE.
2. REPAIR DAMAGED MULLION

5 WINDOW NO. 007A
ROOM 007

NEW WORK NOTES
ALL NEW WORK NOTES SHALL BE CONSIDERED TYPICAL UNLESS NOTED OTHERWISE (U.N.O.)

- 1 RESTORE EXISTING SILL AND REINSTALL.
- 2 NOT USED
- 3 NOT USED
- 4 ROTTED STILE/RAIL IN LOCATION NOTED.
- 5 RESTORE/REPLACE EXISTING WOOD APRON.
- 6 REPLACE ROTTED RAIL MATCH EXISTING.
- 7 REPAIR/REPLACE ROTTED SILL.
- 8 SUSPECTED WATER DAMAGE IN JAMB CONFIRM CONDITION REPAIR/REPLACE BASED ON CONDITION SPLIT SILL REPLACE.
- 9 SILL/SASH ROTTED, REPLACE.
- 10 FURNISH AND INSTALL NEW P.T. WOOD SILL. MATCH DIMENSIONS OF EXISTING.
- 11 REMOVE AND REPLACE EXISTING HEAD JAMB AND SILL FRAMING AGAINST EXISTING BRICK MASONRY W/ PRESSURE TREATED LUMBER. MATCH EXISTING DIMENSIONS OF WOOD FRAMES AND MATCH EXISTING JOINT DETAILS.
- 12 STRAIGHTEN AND LEVEL WINDOW SILL ACROSS FULL LENGTH OF WINDOW ASSEMBLY.
- 13 MISSING APRON. INSTALL NEW APRON TO MATCH EXISTING
- 14 REPAIR/REPLACE MULLION TO MATCH EXISTING.
- 15 REPLACE MISSING TRIM TO MATCH EXISTING (SEE GENERAL NOTES)
- 16 REPAIR AND SMOOTH MULLION TO MATCH EXISTING, READY FOR PAINT (SEE GENERAL NOTES)
- 17 REPLACE ROTTED WINDOW CASING (SEE GENERAL NOTES)
- 18 OPEN TO OUTSIDE, REPAIR AREA TO BE PROPERLY SEALED.
- 19 REPLACE MISSING/DAMAGED CASING TO MATCH EXISTING (SEE GENERAL NOTES)
- 20 REPAIR AND SMOOTH STILE/RAIL TO MATCH EXISTING, READY FOR PAINT (SEE GENERAL NOTES)
- 21 REPAIR SAGGING/WARPED WOOD. STRAIGHTEN TO MATCH EXISTING.
- 22 REPAIR/REPLACE ROTTED HEADER
- 23 REPLACE ROTTED TRIM TO MATCH EXISTING (SEE GENERAL NOTES)
- 24 REPAIR TRIM TO MATCH EXISTING, READY FOR PAINT (SEE GENERAL NOTES)
- 25 REPAIR DAMAGED STOOL TO MATCH EXISTING



EMI
architects

ARCHITECTURE
PLANNING INTERIORS
GRAPHICS

ELLIOTT MARSHALL PINKES PA, (561) 673-1142
251 E. 7TH AVENUE TALLAHASSEE FL 32303
(850) 222-7442
WWW.EMIPROJECTS.COM
LICENSE # A-14320407 # 0201153

NOTE:
11"x17" SHEETS ARE PLOTTED AT 1/2 THE SCALE NOTED ON THESE DRAWINGS.

1

**Florida Department of State
Division of Historical Resources**

**HISTORIC JEFFERSON
COUNTY HIGH SCHOOL
RESTORATION**
MONTICELLO, FLORIDA

OWNER NAME:
**Jefferson County Board of
County Commissioners**
MONTICELLO, FLORIDA

REV	DATE	DESCRIPTION
1	04/20/2023	HURRICANE MICHAEL GRANT

PROJECT PHASE
100% CONSTRUCTION DOCUMENTS

DATE 01 AUGUST 2019	DRAWN BY RMP
PROJECT NO 65000	CHECKED BY SKCC

SHEET TITLE
WINDOW ANALYSIS

SHEET NO A607	REV NO 1
-------------------------	--------------------

NOTE:
11"x17" SHEETS ARE PLOTTED AT 1/2 THE SCALE NOTED ON THESE DRAWINGS.

Florida Department of State
Division of Historical Resources

HISTORIC JEFFERSON COUNTY HIGH SCHOOL RESTORATION

MONTICELLO, FLORIDA
OWNER NAME:
Jefferson County Board of County Commissioners
MONTICELLO, FLORIDA

REV	DATE	DESCRIPTION
△	04/20/2023	HURRICANE MICHAEL GRANT

PROJECT PHASE
100% CONSTRUCTION DOCUMENTS


DATE 01 AUGUST 2019	DRAWN BY RMP
PROJECT NO 65000	CHECKED BY SKC

SHEET TITLE WINDOW ANALYSIS

SHEET NO A608	REV NO △
-------------------------	-------------



IMAGE_101A



WINDOW TYPE

EXISTING GLAZING INVENTORY LEGEND
H= HISTORIC SUITABLE FOR REUSE
B= BROKEN UNSUITABLE FOR REUSE
IN THIS LOCATION (SEE GENERAL NOTES)

- NOTES
- EXISTING WOOD WINDOW SASH, SILL, ETC. COMPONENTS ARE IN GOOD TO FAIR CONDITION AND GENERALLY SUITED FOR RESTORATION AND REUSE UNLESS NOTED OTHERWISE.
 - REPLACE ENTIRE HEAD CASING TO MATCH EXISTING

1

3 WINDOW NO. 101A
ROOM 101

NEW WORK NOTES
ALL NEW WORK NOTES SHALL BE CONSIDERED TYPICAL UNLESS NOTED OTHERWISE (U.N.O.)

- RESTORE EXISTING SILL AND REINSTALL.
- NOT USED
- NOT USED
- ROTTED STILE/RAIL IN LOCATION NOTED.
- RESTORE/REPLACE EXISTING WOOD APRON.
- REPLACE ROTTED RAIL MATCH EXISTING.
- REPAIR/REPLACE ROTTED SILL.
- SUSPECTED WATER DAMAGE IN JAMB CONFIRM CONDITION REPAIR/REPLACE BASED ON CONDITION SPLIT SILL REPLACE.
- SILL/SASH ROTTED, REPLACE.
- FURNISH AND INSTALL NEW P.T. WOOD SILL. MATCH DIMENSIONS OF EXISTING.
- REMOVE AND REPLACE EXISTING HEAD JAMB AND SILL FRAMING AGAINST EXISTING BRICK MASONRY W/ PRESSURE TREATED LUMBER. MATCH EXISTING DIMENSIONS OF WOOD FRAMES AND MATCH EXISTING JOINT DETAILS.
- STRAIGHTEN AND LEVEL WINDOW SILL ACROSS FULL LENGTH OF WINDOW ASSEMBLY.
- MISSING APRON. INSTALL NEW APRON TO MATCH EXISTING
- REPAIR/REPLACE MULLION TO MATCH EXISTING.
- REPLACE MISSING TRIM TO MATCH EXISTING (SEE GENERAL NOTES)
- REPAIR AND SMOOTH MULLION TO MATCH EXISTING, READY FOR PAINT (SEE GENERAL NOTES)
- REPLACE ROTTED WINDOW CASING (SEE GENERAL NOTES)
- OPEN TO OUTSIDE, REPAIR AREA TO BE PROPERLY SEALED.
- REPLACE MISSING/DAMAGED CASING TO MATCH EXISTING (SEE GENERAL NOTES)
- REPAIR AND SMOOTH STILE/RAIL TO MATCH EXISTING, READY FOR PAINT (SEE GENERAL NOTES)
- REPAIR SAGGING/WARPED WOOD. STRAIGHTEN TO MATCH EXISTING.
- REPAIR/REPLACE ROTTED HEADER
- REPLACE ROTTED TRIM TO MATCH EXISTING (SEE GENERAL NOTES)
- REPAIR TRIM TO MATCH EXISTING, READY FOR PAINT (SEE GENERAL NOTES)
- REPAIR DAMAGED STOOL TO MATCH EXISTING



IMAGE_007C




WINDOW TYPE


EXISTING GLAZING INVENTORY LEGEND
H= HISTORIC SUITABLE FOR REUSE
B= BROKEN UNSUITABLE FOR REUSE
IN THIS LOCATION (SEE GENERAL NOTES)

- NOTES
- EXISTING WOOD FRAME, SILL, HARDWARE, ETC. COMPONENTS ARE IN GOOD TO FAIR CONDITION AND GENERALLY SUITED FOR RESTORATION REUSE UNLESS NOTED OTHERWISE.

2 WINDOW NO. 007C
ROOM 007



IMAGE_101C




WINDOW TYPE


EXISTING GLAZING INVENTORY LEGEND
H= HISTORIC SUITABLE FOR REUSE
B= BROKEN UNSUITABLE FOR REUSE
IN THIS LOCATION (SEE GENERAL NOTES)

- NOTES
- EXISTING WOOD WINDOW SASH, SILL, CASING, ETC. COMPONENTS ARE IN GOOD TO FAIR CONDITION AND GENERALLY SUITED FOR RESTORATION AND REUSE UNLESS NOTED OTHERWISE
 - INSPECT SILL AND JAMB FOR WATER DAMAGE. CONFIRM CONDITION REPAIR/REPLACE BASED ON CONDITION.

5 WINDOW NO. 101C
ROOM 101



IMAGE_007B



WINDOW TYPE


EXISTING GLAZING INVENTORY LEGEND
H= HISTORIC SUITABLE FOR REUSE
B= BROKEN UNSUITABLE FOR REUSE
IN THIS LOCATION (SEE GENERAL NOTES)

- NOTES
- EXISTING WOOD FRAME, SILL, HARDWARE, ETC. COMPONENTS ARE IN GOOD TO FAIR CONDITION AND GENERALLY SUITED FOR RESTORATION REUSE UNLESS NOTED OTHERWISE.
 - RESTORE EXISTING SILL TO PREVENT OPENING TO EXTERIOR

1 WINDOW NO. 007B
ROOM 007



IMAGE_101B



WINDOW TYPE

EXISTING GLAZING INVENTORY LEGEND
H= HISTORIC SUITABLE FOR REUSE
B= BROKEN UNSUITABLE FOR REUSE
IN THIS LOCATION (SEE GENERAL NOTES)

- NOTES
- EXISTING WOOD WINDOW SASH, SILL, CASING, ETC. COMPONENTS ARE IN GOOD TO FAIR CONDITION AND GENERALLY SUITED FOR RESTORATION AND REUSE UNLESS NOTED OTHERWISE
 - INSPECT SILL AND JAMB FOR WATER DAMAGE. CONFIRM CONDITION REPAIR/REPLACE BASED ON CONDITION.

4 WINDOW NO. 101B
ROOM 101

NOTE:
11"x17" SHEETS ARE PLOTTED AT 1/2 THE
SCALE NOTED ON THESE DRAWINGS.

Florida Department of State
Division of Historical Resources

**HISTORIC JEFFERSON
COUNTY HIGH SCHOOL
RESTORATION**

MONTEICELLO, FLORIDA
OWNER NAME:
**Jefferson County Board of
County Commissioners**
MONTEICELLO, FLORIDA

REV	DATE	DESCRIPTION
1	04/20/2023	HURRICANE MICHAEL GRANT

PROJECT PHASE
100% CONSTRUCTION DOCUMENTS

DATE 01 AUGUST 2019	DRAWN BY RMP
PROJECT NO 65000	CHECKED BY SKCC

SHEET TITLE
WINDOW ANALYSIS

SHEET NO A609	REV NO 1
-------------------------	-------------

1 WINDOW NO. 103A
ROOM 103

WINDOW TYPE

EXISTING GLAZING INVENTORY LEGEND
H= HISTORIC SUITABLE FOR REUSE
B= BROKEN UNSUITABLE FOR REUSE
IN THIS LOCATION (SEE GENERAL NOTES)

NOTES
1. EXISTING WOOD WINDOW SASH, SILL, CASING, ETC. COMPONENTS ARE IN GOOD TO FAIR CONDITION AND GENERALLY SUITED FOR RESTORATION AND REUSE UNLESS NOTED OTHERWISE.
2. REPLACE MISSING APRON, UNLESS WAINSCOTING TO BE INSTALLED IN ITS PLACE.

2 WINDOW NO. 103B
ROOM 103

WINDOW TYPE

EXISTING GLAZING INVENTORY LEGEND
H= HISTORIC SUITABLE FOR REUSE
B= BROKEN UNSUITABLE FOR REUSE
IN THIS LOCATION (SEE GENERAL NOTES)

NOTES
1. EXISTING WOOD WINDOW SASH, SILL, CASING, ETC. COMPONENTS ARE IN GOOD TO FAIR CONDITION AND GENERALLY SUITED FOR RESTORATION AND REUSE UNLESS NOTED OTHERWISE.
2. REPLACE MISSING APRON, UNLESS WAINSCOTING TO BE INSTALLED IN ITS PLACE.

3 WINDOW NO. 104A
ROOM 104

WINDOW TYPE

EXISTING GLAZING INVENTORY LEGEND
H= HISTORIC SUITABLE FOR REUSE
B= BROKEN UNSUITABLE FOR REUSE
IN THIS LOCATION (SEE GENERAL NOTES)

NOTES
1. EXISTING WOOD WINDOW SASH, SILL, CASING, ETC. COMPONENTS ARE IN GOOD TO FAIR CONDITION AND GENERALLY SUITED FOR RESTORATION AND REUSE UNLESS NOTED OTHERWISE.
2. MINOR SAGGING IN HEAD CASING, REPAIR AND STRAIGHTEN
3. REPLACE MISSING APRON, UNLESS WAINSCOTING TO BE INSTALLED IN ITS PLACE.

4 WINDOW NO. 104B
ROOM 104

WINDOW TYPE

EXISTING GLAZING INVENTORY LEGEND
H= HISTORIC SUITABLE FOR REUSE
B= BROKEN UNSUITABLE FOR REUSE
IN THIS LOCATION (SEE GENERAL NOTES)

NOTES
1. EXISTING WOOD WINDOW SASH, SILL, CASING, ETC. COMPONENTS ARE IN GOOD TO FAIR CONDITION AND GENERALLY SUITED FOR RESTORATION AND REUSE UNLESS NOTED OTHERWISE.
2. MINOR SAGGING IN HEAD CASING, REPAIR AND STRAIGHTEN
3. REPLACE MISSING APRON, UNLESS WAINSCOTING TO BE INSTALLED IN ITS PLACE.
4. REPLACE ROTTEN WOOD BASE FRAMING (SEE GENERAL NOTES)

5 WINDOW NO. 105A
ROOM 105


WINDOW TYPE

EXISTING GLAZING INVENTORY LEGEND
H= HISTORIC SUITABLE FOR REUSE
B= BROKEN UNSUITABLE FOR REUSE
IN THIS LOCATION (SEE GENERAL NOTES)

NOTES
1. EXISTING WOOD WINDOW SASH, SILL, CASING, ETC. COMPONENTS ARE IN GOOD TO FAIR CONDITION AND GENERALLY SUITED FOR RESTORATION AND REUSE UNLESS NOTED OTHERWISE.
2. REPLACE MISSING APRON, UNLESS WAINSCOTING TO BE INSTALLED IN ITS PLACE.

NEW WORK NOTES
ALL NEW WORK NOTES SHALL BE CONSIDERED TYPICAL UNLESS NOTED OTHERWISE (U.N.O.)

- 1 RESTORE EXISTING SILL AND REINSTALL.
- 2 NOT USED
- 3 NOT USED
- 4 ROTTED STILE/RAIL IN LOCATION NOTED.
- 5 RESTORE/REPLACE EXISTING WOOD APRON.
- 6 REPLACE ROTTED RAIL MATCH EXISTING.
- 7 REPAIR/REPLACE ROTTED SILL.
- 8 SUSPECTED WATER DAMAGE IN JAMB CONFIRM CONDITION REPAIR/REPLACE BASED ON CONDITION SPLIT SILL REPLACE.
- 9 SILL/SASH ROTTED, REPLACE.
- 10 FURNISH AND INSTALL NEW P.T. WOOD SILL. MATCH DIMENSIONS OF EXISTING.
- 11 REMOVE AND REPLACE EXISTING HEAD JAMB AND SILL FRAMING AGAINST EXISTING BRICK MASONRY W/ PRESSURE TREATED LUMBER. MATCH EXISTING DIMENSIONS OF WOOD FRAMES AND MATCH EXISTING JOINT DETAILS.
- 12 STRAIGHTEN AND LEVEL WINDOW SILL ACROSS FULL LENGTH OF WINDOW ASSEMBLY.
- 13 MISSING APRON. INSTALL NEW APRON TO MATCH EXISTING
- 14 REPAIR/REPLACE MULLION TO MATCH EXISTING.
- 15 REPLACE MISSING TRIM TO MATCH EXISTING (SEE GENERAL NOTES)
- 16 REPAIR AND SMOOTH MULLION TO MATCH EXISTING, READY FOR PAINT (SEE GENERAL NOTES)
- 17 REPLACE ROTTED WINDOW CASING (SEE GENERAL NOTES)
- 18 OPEN TO OUTSIDE, REPAIR AREA TO BE PROPERLY SEALED.
- 19 REPLACE MISSING/DAMAGED CASING TO MATCH EXISTING (SEE GENERAL NOTES)
- 20 REPAIR AND SMOOTH STILE/RAIL TO MATCH EXISTING, READY FOR PAINT (SEE GENERAL NOTES)
- 21 REPAIR SAGGING/WARPED WOOD. STRAIGHTEN TO MATCH EXISTING.
- 22 REPAIR/REPLACE ROTTED HEADER
- 23 REPLACE ROTTED TRIM TO MATCH EXISTING (SEE GENERAL NOTES)
- 24 REPAIR TRIM TO MATCH EXISTING, READY FOR PAINT (SEE GENERAL NOTES)
- 25 REPAIR DAMAGED STOOL TO MATCH EXISTING



WINDOW TYPE


EXISTING GLAZING INVENTORY LEGEND

H= HISTORIC SUITABLE FOR REUSE
B= BROKEN UNSUITABLE FOR REUSE
IN THIS LOCATION (SEE GENERAL NOTES)

NOTES

1. EXISTING WOOD WINDOW SASH, SILL, CASING, ETC. COMPONENTS ARE IN GOOD TO FAIR CONDITION AND GENERALLY SUITED FOR RESTORATION AND REUSE UNLESS NOTED OTHERWISE.
2. REPLACE MISSING APRON, UNLESS WAINSCOTING TO BE INSTALLED IN ITS PLACE.

1 WINDOW NO. 105B
ROOM 105



WINDOW TYPE


EXISTING GLAZING INVENTORY LEGEND

H= HISTORIC SUITABLE FOR REUSE
B= BROKEN UNSUITABLE FOR REUSE
IN THIS LOCATION (SEE GENERAL NOTES)

NOTES

1. EXISTING WOOD WINDOW SASH, SILL, CASING, ETC. COMPONENTS ARE IN GOOD TO FAIR CONDITION AND GENERALLY SUITED FOR RESTORATION AND REUSE UNLESS NOTED OTHERWISE.
2. REPLACE MISSING APRON, UNLESS WAINSCOTING TO BE INSTALLED IN ITS PLACE.

2 WINDOW NO. 105C
ROOM 105



WINDOW TYPE


EXISTING GLAZING INVENTORY LEGEND

H= HISTORIC SUITABLE FOR REUSE
B= BROKEN UNSUITABLE FOR REUSE
IN THIS LOCATION (SEE GENERAL NOTES)

NOTES

1. EXISTING WOOD WINDOW SASH, SILL, CASING, ETC. COMPONENTS ARE IN GOOD TO FAIR CONDITION AND GENERALLY SUITED FOR RESTORATION AND REUSE UNLESS NOTED OTHERWISE.

3 WINDOW NO. 106A
ROOM 106



WINDOW TYPE


EXISTING GLAZING INVENTORY LEGEND

H= HISTORIC SUITABLE FOR REUSE
B= BROKEN UNSUITABLE FOR REUSE
IN THIS LOCATION (SEE GENERAL NOTES)

NOTES

1. EXISTING WOOD WINDOW SASH, SILL, CASING, ETC. COMPONENTS ARE IN GOOD TO FAIR CONDITION AND GENERALLY SUITED FOR RESTORATION AND REUSE UNLESS NOTED OTHERWISE.
2. REPLACE MISSING APRON, UNLESS WAINSCOTING TO BE INSTALLED IN ITS PLACE.
3. REPLACE ROTTEN WOOD BASE FRAMING (SEE GENERAL NOTES)

4 WINDOW NO. 106B
ROOM 106



WINDOW TYPE

EXISTING GLAZING INVENTORY LEGEND

H= HISTORIC SUITABLE FOR REUSE
B= BROKEN UNSUITABLE FOR REUSE
IN THIS LOCATION (SEE GENERAL NOTES)

NOTES

1. EXISTING WOOD WINDOW SASH, SILL, CASING, ETC. COMPONENTS ARE IN GOOD TO FAIR CONDITION AND GENERALLY SUITED FOR RESTORATION AND REUSE UNLESS NOTED OTHERWISE.
2. REPLACE MISSING APRON, UNLESS WAINSCOTING TO BE INSTALLED IN ITS PLACE.
3. REPLACE WOOD ROT AT HEADER (SEE GENERAL NOTES)


5 WINDOW NO. 106C
ROOM 106

NEW WORK NOTES

ALL NEW WORK NOTES SHALL BE CONSIDERED TYPICAL UNLESS NOTED OTHERWISE (U.N.O.)

- 1 RESTORE EXISTING SILL AND REINSTALL.
- 2 NOT USED
- 3 NOT USED
- 4 ROTTED STILE/RAIL IN LOCATION NOTED.
- 5 RESTORE/REPLACE EXISTING WOOD APRON.
- 6 REPLACE ROTTED RAIL MATCH EXISTING.
- 7 REPAIR/REPLACE ROTTED SILL.
- 8 SUSPECTED WATER DAMAGE IN JAMB CONFIRM CONDITION REPAIR/REPLACE BASED ON CONDITION SPLIT SILL REPLACE.
- 9 SILL/SASH ROTTED, REPLACE.
- 10 FURNISH AND INSTALL NEW P.T. WOOD SILL. MATCH DIMENSIONS OF EXISTING.
- 11 REMOVE AND REPLACE EXISTING HEAD JAMB AND SILL FRAMING AGAINST EXISTING BRICK MASONRY W/ PRESSURE TREATED LUMBER. MATCH EXISTING DIMENSIONS OF WOOD FRAMES AND MATCH EXISTING JOINT DETAILS.
- 12 STRAIGHTEN AND LEVEL WINDOW SILL ACROSS FULL LENGTH OF WINDOW ASSEMBLY.
- 13 MISSING APRON. INSTALL NEW APRON TO MATCH EXISTING
- 14 REPAIR/REPLACE MULLION TO MATCH EXISTING.
- 15 REPLACE MISSING TRIM TO MATCH EXISTING (SEE GENERAL NOTES)
- 16 REPAIR AND SMOOTH MULLION TO MATCH EXISTING, READY FOR PAINT (SEE GENERAL NOTES)
- 17 REPLACE ROTTED WINDOW CASING (SEE GENERAL NOTES)
- 18 OPEN TO OUTSIDE, REPAIR AREA TO BE PROPERLY SEALED.
- 19 REPLACE MISSING/DAMAGED CASING TO MATCH EXISTING (SEE GENERAL NOTES)
- 20 REPAIR AND SMOOTH STILE/RAIL TO MATCH EXISTING, READY FOR PAINT (SEE GENERAL NOTES)
- 21 REPAIR SAGGING/WARPED WOOD. STRAIGHTEN TO MATCH EXISTING.
- 22 REPAIR/REPLACE ROTTED HEADER
- 23 REPLACE ROTTED TRIM TO MATCH EXISTING (SEE GENERAL NOTES)
- 24 REPAIR TRIM TO MATCH EXISTING, READY FOR PAINT (SEE GENERAL NOTES)
- 25 REPAIR DAMAGED STOOL TO MATCH EXISTING

NOTE:
11"x17" SHEETS ARE PLOTTED AT 1/2 THE
SCALE NOTED ON THESE DRAWINGS.



MONTEICELLO, FLORIDA

OWNER NAME:

**Jefferson County Board of
County Commissioners**

MONTEICELLO, FLORIDA

REV	DATE	DESCRIPTION
	04/20/2023	HURRICANE MICHAEL GRANT

PROJECT PHASE

100% CONSTRUCTION DOCUMENTS

DATE

01 AUGUST 2019

DRAWN BY

RMP

PROJECT NO

65000

CHECKED BY


SKC

SHEET TITLE

WINDOW ANALYSIS

SHEET NO
A610

REV NO



WINDOW TYPE


EXISTING GLAZING INVENTORY LEGEND

H= HISTORIC SUITABLE FOR REUSE
B= BROKEN UNSUITABLE FOR REUSE
IN THIS LOCATION (SEE GENERAL NOTES)

NOTES

- EXISTING WOOD WINDOW SASH, CASING, ETC. COMPONENTS ARE IN GOOD TO FAIR CONDITION AND GENERALLY SUITED FOR RESTORATION AND REUSE UNLESS NOTED OTHERWISE.
- REPLACE MISSING APRON, UNLESS WAINSCOTING TO BE INSTALLED IN ITS PLACE.
- REPLACE WOOD ROT AT BASE FRAMING (SEE GENERAL NOTES)

1 WINDOW NO. 106D
ROOM 106



WINDOW TYPE


EXISTING GLAZING INVENTORY LEGEND

H= HISTORIC SUITABLE FOR REUSE
B= BROKEN UNSUITABLE FOR REUSE
IN THIS LOCATION (SEE GENERAL NOTES)

NOTES

- EXISTING WOOD WINDOW SASH, SILL, CASING, ETC. COMPONENTS ARE IN GOOD TO FAIR CONDITION AND GENERALLY SUITED FOR RESTORATION AND REUSE UNLESS NOTED OTHERWISE.
- REPLACE MISSING APRON, UNLESS WAINSCOTING TO BE INSTALLED IN ITS PLACE.
- REPLACE WOOD ROT AT BASE FRAMING (SEE GENERAL NOTES)
- REPAIR AND FIX HOLES IN RAIL AND STILE AT HEAD

2 WINDOW NO. 107A
ROOM 107



WINDOW TYPE


EXISTING GLAZING INVENTORY LEGEND

H= HISTORIC SUITABLE FOR REUSE
B= BROKEN UNSUITABLE FOR REUSE
IN THIS LOCATION (SEE GENERAL NOTES)

NOTES

- EXISTING WOOD WINDOW SASH, SILL, CASING, ETC. COMPONENTS ARE IN GOOD TO FAIR CONDITION AND GENERALLY SUITED FOR RESTORATION AND REUSE UNLESS NOTED OTHERWISE.
- REPLACE MISSING APRON, UNLESS WAINSCOTING TO BE INSTALLED IN ITS PLACE.

3 WINDOW NO. 108A
ROOM 108



WINDOW TYPE


EXISTING GLAZING INVENTORY LEGEND

H= HISTORIC SUITABLE FOR REUSE
B= BROKEN UNSUITABLE FOR REUSE
IN THIS LOCATION (SEE GENERAL NOTES)

NOTES

- EXISTING WOOD WINDOW SASH, SILL, CASING, ETC. COMPONENTS ARE IN GOOD TO FAIR CONDITION AND GENERALLY SUITED FOR RESTORATION AND REUSE UNLESS NOTED OTHERWISE.
- REMOVE CRACKED HISTORIC GLASS TO POSSIBLY BE USED IN SMALLER OPENING (SEE GENERAL NOTES)

4 WINDOW NO. 111A
ROOM 111



WINDOW TYPE

EXISTING GLAZING INVENTORY LEGEND

H= HISTORIC SUITABLE FOR REUSE
B= BROKEN UNSUITABLE FOR REUSE
IN THIS LOCATION (SEE GENERAL NOTES)

NOTES

- EXISTING WOOD WINDOW SASH, SILL, CASING, ETC. COMPONENTS ARE IN GOOD TO FAIR CONDITION AND GENERALLY SUITED FOR RESTORATION AND REUSE UNLESS NOTED OTHERWISE.

5 WINDOW NO. 113A
ROOM 113

NEW WORK NOTES

ALL NEW WORK NOTES SHALL BE CONSIDERED TYPICAL UNLESS NOTED OTHERWISE (U.N.O.)

- RESTORE EXISTING SILL AND REINSTALL.
- NOT USED
- NOT USED
- ROTTED STILE/RAIL IN LOCATION NOTED.
- RESTORE/REPLACE EXISTING WOOD APRON.
- REPLACE ROTTED RAIL MATCH EXISTING.
- REPAIR/REPLACE ROTTED SILL.
- SUSPECTED WATER DAMAGE IN JAMB CONFIRM CONDITION REPAIR/REPLACE BASED ON CONDITION SPLIT SILL REPLACE.
- SILL/SASH ROTTED, REPLACE.
- FURNISH AND INSTALL NEW P.T. WOOD SILL. MATCH DIMENSIONS OF EXISTING.
- REMOVE AND REPLACE EXISTING HEAD JAMB AND SILL FRAMING AGAINST EXISTING BRICK MASONRY W/ PRESSURE TREATED LUMBER. MATCH EXISTING DIMENSIONS OF WOOD FRAMES AND MATCH EXISTING JOINT DETAILS.
- STRAIGHTEN AND LEVEL WINDOW SILL ACROSS FULL LENGTH OF WINDOW ASSEMBLY.
- MISSING APRON. INSTALL NEW APRON TO MATCH EXISTING
- REPAIR/REPLACE MULLION TO MATCH EXISTING.
- REPLACE MISSING TRIM TO MATCH EXISTING (SEE GENERAL NOTES)
- REPAIR AND SMOOTH MULLION TO MATCH EXISTING, READY FOR PAINT (SEE GENERAL NOTES)
- REPLACE ROTTED WINDOW CASING (SEE GENERAL NOTES)
- OPEN TO OUTSIDE, REPAIR AREA TO BE PROPERLY SEALED.
- REPLACE MISSING/DAMAGED CASING TO MATCH EXISTING (SEE GENERAL NOTES)
- REPAIR AND SMOOTH STILE/RAIL TO MATCH EXISTING, READY FOR PAINT (SEE GENERAL NOTES)
- REPAIR SAGGING/WARPED WOOD. STRAIGHTEN TO MATCH EXISTING.
- REPAIR/REPLACE ROTTED HEADER
- REPLACE ROTTED TRIM TO MATCH EXISTING (SEE GENERAL NOTES)
- REPAIR TRIM TO MATCH EXISTING, READY FOR PAINT (SEE GENERAL NOTES)
- REPAIR DAMAGED STOOL TO MATCH EXISTING



ARCHITECTURE
PLANNING INTERIORS
GRAPHICS

ELLIOTT MARSHALL PINES P.A. (BNA 00000000)
251 E. 7TH AVENUE TALLAHASSEE FL 32303
(850) 222-7442
WWW.EMIARCHITECTS.COM
LICENSE #14-C000040P #B-C000153

NOTE:
11"x17" SHEETS ARE PLOTTED AT 1/2 THE SCALE NOTED ON THESE DRAWINGS.

Florida Department of State
Division of Historical Resources

**HISTORIC JEFFERSON
COUNTY HIGH SCHOOL
RESTORATION**

MONTICELLO, FLORIDA

OWNER NAME:
**Jefferson County Board of
County Commissioners**

MONTICELLO, FLORIDA

REV	DATE	DESCRIPTION
	04/20/2023	HURRICANE MICHAEL GRANT

PROJECT PHASE
100% CONSTRUCTION DOCUMENTS

DATE
01 AUGUST 2019

DRAWN BY
RMP



PROJECT NO
65000

CHECKED BY
SKCC

SHEET TITLE
WINDOW ANALYSIS

SHEET NO
A611

REV NO



IMAGE_115A

WINDOW TYPE 3



EXISTING GLAZING INVENTORY LEGEND

H= HISTORIC SUITABLE FOR REUSE
 B= BROKEN UNSUITABLE FOR REUSE
 IN THIS LOCATION (SEE GENERAL NOTES)

NOTES

1. EXISTING WOOD WINDOW SASH, SILL, CASING, ETC. COMPONENTS ARE IN GOOD TO FAIR CONDITION AND GENERALLY SUITED FOR RESTORATION AND REUSE UNLESS NOTED OTHERWISE.

1 WINDOW NO. 115A
ROOM 115



IMAGE_116A

WINDOW TYPE 1



EXISTING GLAZING INVENTORY LEGEND

H= HISTORIC SUITABLE FOR REUSE
 B= BROKEN UNSUITABLE FOR REUSE
 IN THIS LOCATION (SEE GENERAL NOTES)

NOTES

1. EXISTING WOOD WINDOW SASH, SILL, CASING, ETC. COMPONENTS ARE IN GOOD TO FAIR CONDITION AND GENERALLY SUITED FOR RESTORATION AND REUSE UNLESS NOTED OTHERWISE.
2. REPLACE WOOD ROT AT HEADER (SEE GENERAL NOTES)

2 WINDOW NO. 116A
ROOM 116



IMAGE_116B

WINDOW TYPE 1

EXISTING GLAZING INVENTORY LEGEND

H= HISTORIC SUITABLE FOR REUSE
 B= BROKEN UNSUITABLE FOR REUSE
 IN THIS LOCATION (SEE GENERAL NOTES)

NOTES


1. EXISTING WOOD WINDOW SASH, SILL, CASING, ETC. COMPONENTS ARE IN GOOD TO FAIR CONDITION AND GENERALLY SUITED FOR RESTORATION AND REUSE UNLESS NOTED OTHERWISE.
2. REPLACE WOOD ROT AT HEADER (SEE GENERAL NOTES)

3 WINDOW NO. 116B
ROOM 116

NEW WORK NOTES

ALL NEW WORK NOTES SHALL BE CONSIDERED TYPICAL UNLESS NOTED OTHERWISE (U.N.O.)

- 1 RESTORE EXISTING SILL AND REINSTALL.
- 2 NOT USED
- 3 NOT USED
- 4 ROTTED STILE/RAIL IN LOCATION NOTED.
- 5 RESTORE/REPLACE EXISTING WOOD APRON.
- 6 REPLACE ROTTED RAIL MATCH EXISTING.
- 7 REPAIR/REPLACE ROTTED SILL.
- 8 SUSPECTED WATER DAMAGE IN JAMB CONFIRM CONDITION REPAIR/REPLACE BASED ON CONDITION SPLIT SILL REPLACE.
- 9 SILL/SASH ROTTED, REPLACE.
- 10 FURNISH AND INSTALL NEW P.T. WOOD SILL. MATCH DIMENSIONS OF EXISTING.
- 11 REMOVE AND REPLACE EXISTING HEAD JAMB AND SILL FRAMING AGAINST EXISTING BRICK MASONRY W/ PRESSURE TREATED LUMBER. MATCH EXISTING DIMENSIONS OF WOOD FRAMES AND MATCH EXISTING JOINT DETAILS.
- 12 STRAIGHTEN AND LEVEL WINDOW SILL ACROSS FULL LENGTH OF WINDOW ASSEMBLY.
- 13 MISSING APRON. INSTALL NEW APRON TO MATCH EXISTING
- 14 REPAIR/REPLACE MULLION TO MATCH EXISTING.
- 15 REPLACE MISSING TRIM TO MATCH EXISTING (SEE GENERAL NOTES)
- 16 REPAIR AND SMOOTH MULLION TO MATCH EXISTING, READY FOR PAINT (SEE GENERAL NOTES)
- 17 REPLACE ROTTED WINDOW CASING (SEE GENERAL NOTES)
- 18 OPEN TO OUTSIDE, REPAIR AREA TO BE PROPERLY SEALED.
- 19 REPLACE MISSING/DAMAGED CASING TO MATCH EXISTING (SEE GENERAL NOTES)
- 20 REPAIR AND SMOOTH STILE/RAIL TO MATCH EXISTING, READY FOR PAINT (SEE GENERAL NOTES)
- 21 REPAIR SAGGING/WARPED WOOD. STRAIGHTEN TO MATCH EXISTING.
- 22 REPAIR/REPLACE ROTTED HEADER
- 23 REPLACE ROTTED TRIM TO MATCH EXISTING (SEE GENERAL NOTES)
- 24 REPAIR TRIM TO MATCH EXISTING, READY FOR PAINT (SEE GENERAL NOTES)
- 25 REPAIR DAMAGED STOOL TO MATCH EXISTING



IMAGE_116C

WINDOW TYPE 1

EXISTING GLAZING INVENTORY LEGEND

H= HISTORIC SUITABLE FOR REUSE
 B= BROKEN UNSUITABLE FOR REUSE
 IN THIS LOCATION (SEE GENERAL NOTES)

NOTES

1. EXISTING WOOD WINDOW SASH, SILL, CASING, ETC. COMPONENTS ARE IN GOOD TO FAIR CONDITION AND GENERALLY SUITED FOR RESTORATION AND REUSE UNLESS NOTED OTHERWISE.
2. REPLACE WOOD ROT AT HEADER (SEE GENERAL NOTES)

4 WINDOW NO. 116C
ROOM 116



ARCHITECTURE
 PLANNING INTERIORS
 GRAPHICS

ELLIOTT MARSHALL PINKES P.A. (E.M.P.) ARCHITECTS
 251 E. 7TH AVENUE TALLAHASSEE FL 32303
 (850) 222-7442
 WWW.EMIARCHITECTS.COM
 LICENSE #144330040P #0000153

NOTE:
 11"x17" SHEETS ARE PLOTTED AT 1/2 THE
 SCALE NOTED ON THESE DRAWINGS.

Florida Department of State
 Division of Historical Resources

**HISTORIC JEFFERSON
 COUNTY HIGH SCHOOL
 RESTORATION**

MONTEICELLO, FLORIDA

OWNER NAME:

**Jefferson County Board of
 County Commissioners**

MONTEICELLO, FLORIDA

REV	DATE	DESCRIPTION

PROJECT PHASE
 100% CONSTRUCTION DOCUMENTS

DATE
 01 AUGUST 2019

DRAWN BY
 RMP



PROJECT NO
 65000

CHECKED BY
 SKCC

SHEET TITLE
WINDOW ANALYSIS

SHEET NO
A612

REV NO



WINDOW TYPE 1


EXISTING GLAZING INVENTORY LEGEND

H= HISTORIC SUITABLE FOR REUSE
B= BROKEN UNSUITABLE FOR REUSE
IN THIS LOCATION (SEE GENERAL NOTES)

NOTES

- 1. EXISTING WOOD WINDOW SASH, SILL, CASING, ETC. COMPONENTS ARE IN GOOD TO FAIR CONDITION AND GENERALLY SUITED FOR RESTORATION AND REUSE UNLESS NOTED OTHERWISE.
- 2. REPLACE MISSING APRON, UNLESS WAINSCOTING TO BE INSTALLED IN ITS PLACE.
- 3. REPLACE ROTTEN WOOD BASE FRAMING (SEE GENERAL NOTES)

1 WINDOW NO. 201A ROOM 201



WINDOW TYPE 2



EXISTING GLAZING INVENTORY LEGEND

H= HISTORIC SUITABLE FOR REUSE
B= BROKEN UNSUITABLE FOR REUSE
IN THIS LOCATION (SEE GENERAL NOTES)

NOTES

- 1. EXISTING WOOD WINDOW SASH, SILL, CASING, ETC. COMPONENTS ARE IN GOOD TO FAIR CONDITION AND GENERALLY SUITED FOR RESTORATION AND REUSE UNLESS NOTED OTHERWISE.
- 2. REPLACE MISSING APRON, UNLESS WAINSCOTING TO BE INSTALLED IN ITS PLACE.
- 3. REPLACE ROTTEN WOOD BASE FRAMING (SEE GENERAL NOTES)

2 WINDOW NO. 201B ROOM 201



WINDOW TYPE 3

EXISTING GLAZING INVENTORY LEGEND

H= HISTORIC SUITABLE FOR REUSE
B= BROKEN UNSUITABLE FOR REUSE
IN THIS LOCATION (SEE GENERAL NOTES)

NOTES


- 1. EXISTING WOOD WINDOW SASH, SILL, CASING, ETC. COMPONENTS ARE IN GOOD TO FAIR CONDITION AND GENERALLY SUITED FOR RESTORATION AND REUSE UNLESS NOTED OTHERWISE.
- 2. REPLACE MISSING APRON, UNLESS WAINSCOTING TO BE INSTALLED IN ITS PLACE.
- 3. REPLACE ROTTEN WOOD BASE FRAMING (SEE GENERAL NOTES)

3 WINDOW NO. 201C ROOM 201

NEW WORK NOTES

ALL NEW WORK NOTES SHALL BE CONSIDERED TYPICAL UNLESS NOTED OTHERWISE (U.N.O.)

- 1 RESTORE EXISTING SILL AND REINSTALL.
- 2 NOT USED
- 3 NOT USED
- 4 ROTTED STILE/RAIL IN LOCATION NOTED.
- 5 RESTORE/REPLACE EXISTING WOOD APRON.
- 6 REPLACE ROTTED RAIL MATCH EXISTING.
- 7 REPAIR/REPLACE ROTTED SILL.
- 8 SUSPECTED WATER DAMAGE IN JAMB CONFIRM CONDITION REPAIR/REPLACE BASED ON CONDITION SPLIT SILL REPLACE.
- 9 SILL/SASH ROTTED, REPLACE.
- 10 FURNISH AND INSTALL NEW P.T. WOOD SILL. MATCH DIMENSIONS OF EXISTING.
- 11 REMOVE AND REPLACE EXISTING HEAD JAMB AND SILL FRAMING AGAINST EXISTING BRICK MASONRY W/ PRESSURE TREATED LUMBER. MATCH EXISTING DIMENSIONS OF WOOD FRAMES AND MATCH EXISTING JOINT DETAILS.
- 12 STRAIGHTEN AND LEVEL WINDOW SILL ACROSS FULL LENGTH OF WINDOW ASSEMBLY.
- 13 MISSING APRON. INSTALL NEW APRON TO MATCH EXISTING
- 14 REPAIR/REPLACE MULLION TO MATCH EXISTING.
- 15 REPLACE MISSING TRIM TO MATCH EXISTING (SEE GENERAL NOTES)
- 16 REPAIR AND SMOOTH MULLION TO MATCH EXISTING, READY FOR PAINT (SEE GENERAL NOTES)
- 17 REPLACE ROTTED WINDOW CASING (SEE GENERAL NOTES)
- 18 OPEN TO OUTSIDE, REPAIR AREA TO BE PROPERLY SEALED.
- 19 REPLACE MISSING/DAMAGED CASING TO MATCH EXISTING (SEE GENERAL NOTES)
- 20 REPAIR AND SMOOTH STILE/RAIL TO MATCH EXISTING, READY FOR PAINT (SEE GENERAL NOTES)
- 21 REPAIR SAGGING/WARPED WOOD. STRAIGHTEN TO MATCH EXISTING.
- 22 REPAIR/REPLACE ROTTED HEADER
- 23 REPLACE ROTTED TRIM TO MATCH EXISTING (SEE GENERAL NOTES)
- 24 REPAIR TRIM TO MATCH EXISTING, READY FOR PAINT (SEE GENERAL NOTES)
- 25 REPAIR DAMAGED STOOL TO MATCH EXISTING



WINDOW TYPE 3


EXISTING GLAZING INVENTORY LEGEND

H= HISTORIC SUITABLE FOR REUSE
B= BROKEN UNSUITABLE FOR REUSE
IN THIS LOCATION (SEE GENERAL NOTES)

NOTES

- 1. EXISTING WOOD WINDOW SASH, SILL, CASING, ETC. COMPONENTS ARE IN GOOD TO FAIR CONDITION AND GENERALLY SUITED FOR RESTORATION AND REUSE UNLESS NOTED OTHERWISE.
- 2. REPLACE MISSING APRON, UNLESS WAINSCOTING TO BE INSTALLED IN ITS PLACE.

4 WINDOW NO. 205A ROOM 205



WINDOW TYPE 1

EXISTING GLAZING INVENTORY LEGEND

H= HISTORIC SUITABLE FOR REUSE
B= BROKEN UNSUITABLE FOR REUSE
IN THIS LOCATION (SEE GENERAL NOTES)

NOTES

- 1. EXISTING WOOD WINDOW SASH, SILL, CASING, ETC. COMPONENTS ARE IN GOOD TO FAIR CONDITION AND GENERALLY SUITED FOR RESTORATION AND REUSE UNLESS NOTED OTHERWISE.
- 2. REPLACE MISSING APRON, UNLESS WAINSCOTING TO BE INSTALLED IN ITS PLACE.
- 3. REPLACE ROTTEN WOOD BASE FRAMING (SEE GENERAL NOTES)

5 WINDOW NO. 206A ROOM 206

EMI architects ARCHITECTURE PLANNING INTERIORS GRAPHICS 251 E. 7TH AVENUE TALLAHASSEE FL 32303 (850) 222-7442 www.emiarchitects.com LICENSE # A 432048P B 000153

NOTE: 11"x17" SHEETS ARE PLOTTED AT 1/2 THE SCALE NOTED ON THESE DRAWINGS.

Florida Department of State Division of Historical Resources

HISTORIC JEFFERSON COUNTY HIGH SCHOOL RESTORATION

MONTICELLO, FLORIDA OWNER NAME: Jefferson County Board of County Commissioners MONTICELLO, FLORIDA

REV	DATE	DESCRIPTION

PROJECT PHASE 100% CONSTRUCTION DOCUMENTS

DATE 01 AUGUST 2019	DRAWN BY RMP
PROJECT NO 65000	CHECKED BY SKCC

SHEET TITLE WINDOW ANALYSIS

SHEET NO A613	REV NO
---------------	--------

NOTE:
11"x17" SHEETS ARE PLOTTED AT 1/2 THE SCALE NOTED ON THESE DRAWINGS.

Florida Department of State
Division of Historical Resources

HISTORIC JEFFERSON COUNTY HIGH SCHOOL RESTORATION

MONTEICELLO, FLORIDA
OWNER NAME:
Jefferson County Board of County Commissioners
MONTEICELLO, FLORIDA

REV	DATE	DESCRIPTION

PROJECT PHASE
100% CONSTRUCTION DOCUMENTS

DATE
01 AUGUST 2019

DRAWN BY
RMP


PROJECT NO
65000

CHECKED BY
SKCC

SHEET TITLE
WINDOW ANALYSIS

SHEET NO
A614

REV NO



WINDOW TYPE 1


EXISTING GLAZING INVENTORY LEGEND
H= HISTORIC SUITABLE FOR REUSE
B= BROKEN UNSUITABLE FOR REUSE
IN THIS LOCATION (SEE GENERAL NOTES)

NOTES
1. EXISTING WOOD WINDOW SASH, SILL, CASING, ETC. COMPONENTS ARE IN GOOD TO FAIR CONDITION AND GENERALLY SUITED FOR RESTORATION AND REUSE UNLESS NOTED OTHERWISE.
2. REPLACE MISSING APRON, UNLESS WAINSCOTING TO BE INSTALLED IN ITS PLACE.
3. MISSING SHIM AT BASE FRAMING, REPLACE TO MATCH EXISTING

3 WINDOW NO. 207A
ROOM 207

NEW WORK NOTES
ALL NEW WORK NOTES SHALL BE CONSIDERED TYPICAL UNLESS NOTED OTHERWISE (U.N.O.)

- 1 RESTORE EXISTING SILL AND REINSTALL.
- 2 NOT USED
- 3 NOT USED
- 4 ROTTED STILE/RAIL IN LOCATION NOTED.
- 5 RESTORE/REPLACE EXISTING WOOD APRON.
- 6 REPLACE ROTTED RAIL MATCH EXISTING.
- 7 REPAIR/REPLACE ROTTED SILL.
- 8 SUSPECTED WATER DAMAGE IN JAMB CONFIRM CONDITION REPAIR/REPLACE BASED ON CONDITION SPLIT SILL REPLACE.
- 9 SILL/SASH ROTTED, REPLACE.
- 10 FURNISH AND INSTALL NEW P.T. WOOD SILL. MATCH DIMENSIONS OF EXISTING.
- 11 REMOVE AND REPLACE EXISTING HEAD JAMB AND SILL FRAMING AGAINST EXISTING BRICK MASONRY W/ PRESSURE TREATED LUMBER. MATCH EXISTING DIMENSIONS OF WOOD FRAMES AND MATCH EXISTING JOINT DETAILS.
- 12 STRAIGHTEN AND LEVEL WINDOW SILL ACROSS FULL LENGTH OF WINDOW ASSEMBLY.
- 13 MISSING APRON. INSTALL NEW APRON TO MATCH EXISTING
- 14 REPAIR/REPLACE MULLION TO MATCH EXISTING.
- 15 REPLACE MISSING TRIM TO MATCH EXISTING (SEE GENERAL NOTES)
- 16 REPAIR AND SMOOTH MULLION TO MATCH EXISTING, READY FOR PAINT (SEE GENERAL NOTES)
- 17 REPLACE ROTTED WINDOW CASING (SEE GENERAL NOTES)
- 18 OPEN TO OUTSIDE, REPAIR AREA TO BE PROPERLY SEALED.
- 19 REPLACE MISSING/DAMAGED CASING TO MATCH EXISTING (SEE GENERAL NOTES)
- 20 REPAIR AND SMOOTH STILE/RAIL TO MATCH EXISTING, READY FOR PAINT (SEE GENERAL NOTES)
- 21 REPAIR SAGGING/WARPED WOOD. STRAIGHTEN TO MATCH EXISTING.
- 22 REPAIR/REPLACE ROTTED HEADER
- 23 REPLACE ROTTED TRIM TO MATCH EXISTING (SEE GENERAL NOTES)
- 24 REPAIR TRIM TO MATCH EXISTING, READY FOR PAINT (SEE GENERAL NOTES)
- 25 REPAIR DAMAGED STOOL TO MATCH EXISTING




WINDOW TYPE 1

EXISTING GLAZING INVENTORY LEGEND
H= HISTORIC SUITABLE FOR REUSE
B= BROKEN UNSUITABLE FOR REUSE
IN THIS LOCATION (SEE GENERAL NOTES)

NOTES
1. EXISTING WOOD WINDOW SASH, SILL, CASING, ETC. COMPONENTS ARE IN GOOD TO FAIR CONDITION AND GENERALLY SUITED FOR RESTORATION AND REUSE UNLESS NOTED OTHERWISE.
2. REPLACE MISSING APRON, UNLESS WAINSCOTING TO BE INSTALLED IN ITS PLACE.
3. REPLACE ROTTEN WOOD BASE FRAMING (SEE GENERAL NOTES)

2 WINDOW NO. 206C
ROOM 206




WINDOW TYPE 1

EXISTING GLAZING INVENTORY LEGEND
H= HISTORIC SUITABLE FOR REUSE
B= BROKEN UNSUITABLE FOR REUSE
IN THIS LOCATION (SEE GENERAL NOTES)

NOTES
1. EXISTING WOOD WINDOW SASH, SILL, CASING, ETC. COMPONENTS ARE IN GOOD TO FAIR CONDITION AND GENERALLY SUITED FOR RESTORATION AND REUSE UNLESS NOTED OTHERWISE.
2. REPLACE MISSING APRON, UNLESS WAINSCOTING TO BE INSTALLED IN ITS PLACE.

5 WINDOW NO. 207C
ROOM 207




WINDOW TYPE 1

EXISTING GLAZING INVENTORY LEGEND
H= HISTORIC SUITABLE FOR REUSE
B= BROKEN UNSUITABLE FOR REUSE
IN THIS LOCATION (SEE GENERAL NOTES)

NOTES
1. EXISTING WOOD WINDOW SASH, SILL, CASING, ETC. COMPONENTS ARE IN GOOD TO FAIR CONDITION AND GENERALLY SUITED FOR RESTORATION AND REUSE UNLESS NOTED OTHERWISE.
2. REPLACE MISSING APRON, UNLESS WAINSCOTING TO BE INSTALLED IN ITS PLACE.
3. REPLACE ROTTEN WOOD BASE FRAMING (SEE GENERAL NOTES)

1 WINDOW NO. 206B
ROOM 206




WINDOW TYPE 1

EXISTING GLAZING INVENTORY LEGEND
H= HISTORIC SUITABLE FOR REUSE
B= BROKEN UNSUITABLE FOR REUSE
IN THIS LOCATION (SEE GENERAL NOTES)

NOTES
1. EXISTING WOOD WINDOW SASH, SILL, CASING, ETC. COMPONENTS ARE IN GOOD TO FAIR CONDITION AND GENERALLY SUITED FOR RESTORATION AND REUSE UNLESS NOTED OTHERWISE.
2. REPLACE MISSING APRON, UNLESS WAINSCOTING TO BE INSTALLED IN ITS PLACE.

4 WINDOW NO. 207B
ROOM 207



WINDOW TYPE


EXISTING GLAZING INVENTORY LEGEND

H= HISTORIC SUITABLE FOR REUSE
B= BROKEN UNSUITABLE FOR REUSE
IN THIS LOCATION (SEE GENERAL NOTES)

NOTES

1. EXISTING WOOD WINDOW SASH, SILL, CASING, ETC. COMPONENTS ARE IN GOOD TO FAIR CONDITION AND GENERALLY SUITED FOR RESTORATION AND REUSE UNLESS NOTED OTHERWISE.
2. REPLACE MISSING APRON, UNLESS WAINSCOTING TO BE INSTALLED IN ITS PLACE.
3. REMOVE CRACKED HISTORIC GLASS TO POSSIBLY BE USED IN SMALLER OPENING (SEE GENERAL NOTES)

1 WINDOW NO. 207D
ROOM 207



WINDOW TYPE


EXISTING GLAZING INVENTORY LEGEND

H= HISTORIC SUITABLE FOR REUSE
B= BROKEN UNSUITABLE FOR REUSE
IN THIS LOCATION (SEE GENERAL NOTES)

NOTES

1. EXISTING WOOD WINDOW SASH, SILL, CASING, ETC. COMPONENTS ARE IN GOOD TO FAIR CONDITION AND GENERALLY SUITED FOR RESTORATION AND REUSE UNLESS NOTED OTHERWISE.
2. REPLACE MISSING APRON, UNLESS WAINSCOTING TO BE INSTALLED IN ITS PLACE.

2 WINDOW NO. 207E
ROOM 207



WINDOW TYPE


EXISTING GLAZING INVENTORY LEGEND

H= HISTORIC SUITABLE FOR REUSE
B= BROKEN UNSUITABLE FOR REUSE
IN THIS LOCATION (SEE GENERAL NOTES)

NOTES

1. EXISTING WOOD WINDOW SASH, SILL, CASING, ETC. COMPONENTS ARE IN GOOD TO FAIR CONDITION AND GENERALLY SUITED FOR RESTORATION AND REUSE UNLESS NOTED OTHERWISE.
2. REPLACE MISSING APRON, UNLESS WAINSCOTING TO BE INSTALLED IN ITS PLACE.
3. MISSING BASE FRAMING, REPLACE TO MATCH EXISTING

3 WINDOW NO. 207F
ROOM 207



WINDOW TYPE


EXISTING GLAZING INVENTORY LEGEND

H= HISTORIC SUITABLE FOR REUSE
B= BROKEN UNSUITABLE FOR REUSE
IN THIS LOCATION (SEE GENERAL NOTES)

NOTES

1. EXISTING WOOD WINDOW SASH, SILL, CASING, ETC. COMPONENTS ARE IN GOOD TO FAIR CONDITION AND GENERALLY SUITED FOR RESTORATION AND REUSE UNLESS NOTED OTHERWISE.
2. REPLACE MISSING APRON, UNLESS WAINSCOTING TO BE INSTALLED IN ITS PLACE.

4 WINDOW NO. 207G
ROOM 207



WINDOW TYPE

EXISTING GLAZING INVENTORY LEGEND

H= HISTORIC SUITABLE FOR REUSE
B= BROKEN UNSUITABLE FOR REUSE
IN THIS LOCATION (SEE GENERAL NOTES)

NOTES

1. EXISTING WOOD WINDOW SASH, CASING, ETC. COMPONENTS ARE IN GOOD TO FAIR CONDITION AND GENERALLY SUITED FOR RESTORATION AND REUSE UNLESS NOTED OTHERWISE.
2. REPLACE MISSING APRON, UNLESS WAINSCOTING TO BE INSTALLED IN ITS PLACE.
3. REPLACE ROTTEN WOOD BASE FRAMING (SEE GENERAL NOTES)

5 WINDOW NO. 207H
ROOM 207

NEW WORK NOTES

ALL NEW WORK NOTES SHALL BE CONSIDERED TYPICAL UNLESS NOTED OTHERWISE (U.N.O.)

- 1 RESTORE EXISTING SILL AND REINSTALL.
- 2 NOT USED
- 3 NOT USED
- 4 ROTTED STILE/RAIL IN LOCATION NOTED.
- 5 RESTORE/REPLACE EXISTING WOOD APRON.
- 6 REPLACE ROTTED RAIL MATCH EXISTING.
- 7 REPAIR/REPLACE ROTTED SILL.
- 8 SUSPECTED WATER DAMAGE IN JAMB CONFIRM CONDITION REPAIR/REPLACE BASED ON CONDITION SPLIT SILL REPLACE.
- 9 SILL/SASH ROTTED, REPLACE.
- 10 FURNISH AND INSTALL NEW P.T. WOOD SILL. MATCH DIMENSIONS OF EXISTING.
- 11 REMOVE AND REPLACE EXISTING HEAD JAMB AND SILL FRAMING AGAINST EXISTING BRICK MASONRY W/ PRESSURE TREATED LUMBER. MATCH EXISTING DIMENSIONS OF WOOD FRAMES AND MATCH EXISTING JOINT DETAILS.
- 12 STRAIGHTEN AND LEVEL WINDOW SILL ACROSS FULL LENGTH OF WINDOW ASSEMBLY.
- 13 MISSING APRON. INSTALL NEW APRON TO MATCH EXISTING
- 14 REPAIR/REPLACE MULLION TO MATCH EXISTING.
- 15 REPLACE MISSING TRIM TO MATCH EXISTING (SEE GENERAL NOTES)
- 16 REPAIR AND SMOOTH MULLION TO MATCH EXISTING, READY FOR PAINT (SEE GENERAL NOTES)
- 17 REPLACE ROTTED WINDOW CASING (SEE GENERAL NOTES)
- 18 OPEN TO OUTSIDE, REPAIR AREA TO BE PROPERLY SEALED.
- 19 REPLACE MISSING/DAMAGED CASING TO MATCH EXISTING (SEE GENERAL NOTES)
- 20 REPAIR AND SMOOTH STILE/RAIL TO MATCH EXISTING, READY FOR PAINT (SEE GENERAL NOTES)
- 21 REPAIR SAGGING/WARPED WOOD. STRAIGHTEN TO MATCH EXISTING.
- 22 REPAIR/REPLACE ROTTED HEADER
- 23 REPLACE ROTTED TRIM TO MATCH EXISTING (SEE GENERAL NOTES)
- 24 REPAIR TRIM TO MATCH EXISTING, READY FOR PAINT (SEE GENERAL NOTES)
- 25 REPAIR DAMAGED STOOL TO MATCH EXISTING



ARCHITECTURE
PLANNING INTERIORS
GRAPHICS

ELLIOTT MARSHALL PINES P.A. (E.M.P.) ARCHITECTS
251 E. 7TH AVENUE TALLAHASSEE FL 32303
(850) 222-7442
www.emipines.com
LICENSE #144030040P #0000153

NOTE:
11"x17" SHEETS ARE PLOTTED AT 1/2 THE
SCALE NOTED ON THESE DRAWINGS.

Florida Department of State
Division of Historical Resources

**HISTORIC JEFFERSON
COUNTY HIGH SCHOOL
RESTORATION**

MONTICELLO, FLORIDA
OWNER NAME:
**Jefferson County Board of
County Commissioners**
MONTICELLO, FLORIDA

REV	DATE	DESCRIPTION

PROJECT PHASE
100% CONSTRUCTION DOCUMENTS
DATE
01 AUGUST 2019
DRAWN BY
RMP
PROJECT NO
65000
CHECKED BY
SKCC

SHEET TITLE
WINDOW ANALYSIS

SHEET NO
A615
REV NO

NOTE:
11"x17" SHEETS ARE PLOTTED AT 1/2 THE
SCALE NOTED ON THESE DRAWINGS.

1

Florida Department of State
Division of Historical Resources

**HISTORIC JEFFERSON
COUNTY HIGH SCHOOL
RESTORATION**

MONTEICELLO, FLORIDA

OWNER NAME:

**Jefferson County Board of
County Commissioners**

MONTEICELLO, FLORIDA

REV	DATE	DESCRIPTION
1	04/20/2023	HURRICANE MICHAEL GRANT

PROJECT PHASE
100% CONSTRUCTION DOCUMENTS

DATE
01 AUGUST 2019

DRAWN BY
RMP

PROJECT NO
65000

CHECKED BY
SKCC


SHEET TITLE
WINDOW ANALYSIS

SHEET NO
A616

REV NO
1



IMAGE_208A



WINDOW TYPE 1

EXISTING GLAZING INVENTORY LEGEND

H= HISTORIC SUITABLE FOR REUSE
B= BROKEN UNSUITABLE FOR REUSE
IN THIS LOCATION (SEE GENERAL NOTES)


NOTES

- EXISTING WOOD WINDOW SASH, SILL, CASING, ETC. COMPONENTS ARE IN GOOD TO FAIR CONDITION AND GENERALLY SUITED FOR RESTORATION AND REUSE UNLESS NOTED OTHERWISE.
- REPLACE MISSING APRON, UNLESS WAINSCOTING TO BE INSTALLED IN ITS PLACE.
- REPLACE ROTTEN WOOD BASE FRAMING (SEE GENERAL NOTES)

3 WINDOW NO. 208A
ROOM 208



IMAGE_207J



WINDOW TYPE 1

EXISTING GLAZING INVENTORY LEGEND

H= HISTORIC SUITABLE FOR REUSE
B= BROKEN UNSUITABLE FOR REUSE
IN THIS LOCATION (SEE GENERAL NOTES)


NOTES

- EXISTING WOOD WINDOW SASH, SILL, CASING, ETC. COMPONENTS ARE IN GOOD TO FAIR CONDITION AND GENERALLY SUITED FOR RESTORATION AND REUSE UNLESS NOTED OTHERWISE.
- REPLACE MISSING APRON, UNLESS WAINSCOTING TO BE INSTALLED IN ITS PLACE.
- MISSING BASE FRAMING, REPLACE TO MATCH EXISTING

2 WINDOW NO. 207J
ROOM 207



IMAGE_207I



WINDOW TYPE 1

EXISTING GLAZING INVENTORY LEGEND

H= HISTORIC SUITABLE FOR REUSE
B= BROKEN UNSUITABLE FOR REUSE
IN THIS LOCATION (SEE GENERAL NOTES)


NOTES

- EXISTING WOOD WINDOW SASH, SILL, CASING, ETC. COMPONENTS ARE IN GOOD TO FAIR CONDITION AND GENERALLY SUITED FOR RESTORATION AND REUSE UNLESS NOTED OTHERWISE.
- REPLACE MISSING APRON, UNLESS WAINSCOTING TO BE INSTALLED IN ITS PLACE.
- MISSING BASE FRAMING, REPLACE TO MATCH EXISTING

1 WINDOW NO. 207I
ROOM 207



IMAGE_208C



WINDOW TYPE 1

EXISTING GLAZING INVENTORY LEGEND

H= HISTORIC SUITABLE FOR REUSE
B= BROKEN UNSUITABLE FOR REUSE
IN THIS LOCATION (SEE GENERAL NOTES)


NOTES

- EXISTING WOOD WINDOW SASH, SILL, CASING, ETC. COMPONENTS ARE IN GOOD TO FAIR CONDITION AND GENERALLY SUITED FOR RESTORATION AND REUSE UNLESS NOTED OTHERWISE.
- REPLACE MISSING APRON, UNLESS WAINSCOTING TO BE INSTALLED IN ITS PLACE.

5 WINDOW NO. 208C
ROOM 208



IMAGE_208B



WINDOW TYPE 1

EXISTING GLAZING INVENTORY LEGEND

H= HISTORIC SUITABLE FOR REUSE
B= BROKEN UNSUITABLE FOR REUSE
IN THIS LOCATION (SEE GENERAL NOTES)

NOTES

- EXISTING WOOD WINDOW SASH, SILL, CASING, ETC. COMPONENTS ARE IN GOOD TO FAIR CONDITION AND GENERALLY SUITED FOR RESTORATION AND REUSE UNLESS NOTED OTHERWISE.
- REPLACE MISSING APRON, UNLESS WAINSCOTING TO BE INSTALLED IN ITS PLACE.
- REPLACE ROTTEN WOOD BASE FRAMING (SEE GENERAL NOTES)

4 WINDOW NO. 208B
ROOM 208

NEW WORK NOTES

ALL NEW WORK NOTES SHALL BE CONSIDERED TYPICAL UNLESS NOTED OTHERWISE (U.N.O.)

- RESTORE EXISTING SILL AND REINSTALL.
- NOT USED
- NOT USED
- ROTTED STILE/RAIL IN LOCATION NOTED.
- RESTORE/REPLACE EXISTING WOOD APRON.
- REPLACE ROTTED RAIL MATCH EXISTING.
- REPAIR/REPLACE ROTTED SILL.
- SUSPECTED WATER DAMAGE IN JAMB CONFIRM CONDITION REPAIR/REPLACE BASED ON CONDITION SPLIT SILL REPLACE.
- SILL/SASH ROTTED, REPLACE.
- FURNISH AND INSTALL NEW P.T. WOOD SILL. MATCH DIMENSIONS OF EXISTING.
- REMOVE AND REPLACE EXISTING HEAD JAMB AND SILL FRAMING AGAINST EXISTING BRICK MASONRY W/ PRESSURE TREATED LUMBER. MATCH EXISTING DIMENSIONS OF WOOD FRAMES AND MATCH EXISTING JOINT DETAILS.
- STRAIGHTEN AND LEVEL WINDOW SILL ACROSS FULL LENGTH OF WINDOW ASSEMBLY.
- MISSING APRON. INSTALL NEW APRON TO MATCH EXISTING
- REPAIR/REPLACE MULLION TO MATCH EXISTING.
- REPLACE MISSING TRIM TO MATCH EXISTING (SEE GENERAL NOTES)
- REPAIR AND SMOOTH MULLION TO MATCH EXISTING, READY FOR PAINT (SEE GENERAL NOTES)
- REPLACE ROTTED WINDOW CASING (SEE GENERAL NOTES)
- OPEN TO OUTSIDE, REPAIR AREA TO BE PROPERLY SEALED.
- REPLACE MISSING/DAMAGED CASING TO MATCH EXISTING (SEE GENERAL NOTES)
- REPAIR AND SMOOTH STILE/RAIL TO MATCH EXISTING, READY FOR PAINT (SEE GENERAL NOTES)
- REPAIR SAGGING/WARPED WOOD. STRAIGHTEN TO MATCH EXISTING.
- REPAIR/REPLACE ROTTED HEADER
- REPLACE ROTTED TRIM TO MATCH EXISTING (SEE GENERAL NOTES)
- REPAIR TRIM TO MATCH EXISTING, READY FOR PAINT (SEE GENERAL NOTES)
- REPAIR DAMAGED STOOL TO MATCH EXISTING

NOTE:
11"x17" SHEETS ARE PLOTTED AT 1/2 THE SCALE NOTED ON THESE DRAWINGS.

1

Florida Department of State
Division of Historical Resources

**HISTORIC JEFFERSON
COUNTY HIGH SCHOOL
RESTORATION**

MONTEICELLO, FLORIDA

OWNER NAME:

**Jefferson County Board of
County Commissioners**

MONTEICELLO, FLORIDA

REV	DATE	DESCRIPTION
1	04/20/2023	HURRICANE MICHAEL GRANT


PROJECT PHASE
100% CONSTRUCTION DOCUMENTS

DATE: 01 AUGUST 2019 DRAWN BY: RMP

PROJECT NO: 65000 CHECKED BY: SKCC

SHEET TITLE
WINDOW ANALYSIS

SHEET NO: **A617** REV NO: 1



WINDOW NO. 209C
ROOM 209

WINDOW TYPE


EXISTING GLAZING INVENTORY LEGEND
H= HISTORIC SUITABLE FOR REUSE
B= BROKEN UNSUITABLE FOR REUSE
IN THIS LOCATION (SEE GENERAL NOTES)

NOTES
1. EXISTING WOOD WINDOW SASH, SILL, CASING, ETC. COMPONENTS ARE IN GOOD TO FAIR CONDITION AND GENERALLY SUITED FOR RESTORATION AND REUSE UNLESS NOTED OTHERWISE.
2. REPLACE MISSING APRON, UNLESS WAINSCOTING TO BE INSTALLED IN ITS PLACE.

3 WINDOW NO. 209C
ROOM 209

NEW WORK NOTES
ALL NEW WORK NOTES SHALL BE CONSIDERED TYPICAL UNLESS NOTED OTHERWISE (U.N.O.)

- 1 RESTORE EXISTING SILL AND REINSTALL.
- 2 NOT USED
- 3 NOT USED
- 4 ROTTED STILE/RAIL IN LOCATION NOTED.
- 5 RESTORE/REPLACE EXISTING WOOD APRON.
- 6 REPLACE ROTTED RAIL MATCH EXISTING.
- 7 REPAIR/REPLACE ROTTED SILL.
- 8 SUSPECTED WATER DAMAGE IN JAMB CONFIRM CONDITION REPAIR/REPLACE BASED ON CONDITION SPLIT SILL REPLACE.
- 9 SILL/SASH ROTTED, REPLACE.
- 10 FURNISH AND INSTALL NEW P.T. WOOD SILL. MATCH DIMENSIONS OF EXISTING.
- 11 REMOVE AND REPLACE EXISTING HEAD JAMB AND SILL FRAMING AGAINST EXISTING BRICK MASONRY W/ PRESSURE TREATED LUMBER. MATCH EXISTING DIMENSIONS OF WOOD FRAMES AND MATCH EXISTING JOINT DETAILS.
- 12 STRAIGHTEN AND LEVEL WINDOW SILL ACROSS FULL LENGTH OF WINDOW ASSEMBLY.
- 13 MISSING APRON. INSTALL NEW APRON TO MATCH EXISTING
- 14 REPAIR/REPLACE MULLION TO MATCH EXISTING.
- 15 REPLACE MISSING TRIM TO MATCH EXISTING (SEE GENERAL NOTES)
- 16 REPAIR AND SMOOTH MULLION TO MATCH EXISTING, READY FOR PAINT (SEE GENERAL NOTES)
- 17 REPLACE ROTTED WINDOW CASING (SEE GENERAL NOTES)
- 18 OPEN TO OUTSIDE, REPAIR AREA TO BE PROPERLY SEALED.
- 19 REPLACE MISSING/DAMAGED CASING TO MATCH EXISTING (SEE GENERAL NOTES)
- 20 REPAIR AND SMOOTH STILE/RAIL TO MATCH EXISTING, READY FOR PAINT (SEE GENERAL NOTES)
- 21 REPAIR SAGGING/WARPED WOOD. STRAIGHTEN TO MATCH EXISTING.
- 22 REPAIR/REPLACE ROTTED HEADER
- 23 REPLACE ROTTED TRIM TO MATCH EXISTING (SEE GENERAL NOTES)
- 24 REPAIR TRIM TO MATCH EXISTING, READY FOR PAINT (SEE GENERAL NOTES)
- 25 REPAIR DAMAGED STOOL TO MATCH EXISTING




WINDOW NO. 209B
ROOM 209

WINDOW TYPE

EXISTING GLAZING INVENTORY LEGEND
H= HISTORIC SUITABLE FOR REUSE
B= BROKEN UNSUITABLE FOR REUSE
IN THIS LOCATION (SEE GENERAL NOTES)

NOTES
1. EXISTING WOOD WINDOW SASH, SILL, CASING, ETC. COMPONENTS ARE IN GOOD TO FAIR CONDITION AND GENERALLY SUITED FOR RESTORATION AND REUSE UNLESS NOTED OTHERWISE.
2. REPLACE MISSING APRON, UNLESS WAINSCOTING TO BE INSTALLED IN ITS PLACE.

2 WINDOW NO. 209B
ROOM 209




WINDOW NO. 209A
ROOM 209

WINDOW TYPE

EXISTING GLAZING INVENTORY LEGEND
H= HISTORIC SUITABLE FOR REUSE
B= BROKEN UNSUITABLE FOR REUSE
IN THIS LOCATION (SEE GENERAL NOTES)

NOTES
1. EXISTING WOOD WINDOW SASH, SILL, CASING, ETC. COMPONENTS ARE IN GOOD TO FAIR CONDITION AND GENERALLY SUITED FOR RESTORATION AND REUSE UNLESS NOTED OTHERWISE.
2. REPLACE MISSING APRON, UNLESS WAINSCOTING TO BE INSTALLED IN ITS PLACE.
3. REPLACE ROTTEN WOOD BASE FRAMING (SEE GENERAL NOTES)
4. REPAIR AND FIX HOLES IN RAIL AND STILE AT HEAD

1 WINDOW NO. 209A
ROOM 209




WINDOW NO. 209D
ROOM 209

WINDOW TYPE

EXISTING GLAZING INVENTORY LEGEND
H= HISTORIC SUITABLE FOR REUSE
B= BROKEN UNSUITABLE FOR REUSE
IN THIS LOCATION (SEE GENERAL NOTES)

NOTES
1. EXISTING WOOD WINDOW SASH, SILL, CASING, ETC. COMPONENTS ARE IN GOOD TO FAIR CONDITION AND GENERALLY SUITED FOR RESTORATION AND REUSE UNLESS NOTED OTHERWISE.
2. REPLACE MISSING APRON, UNLESS WAINSCOTING TO BE INSTALLED IN ITS PLACE.
3. MISSING SHIM AT BASE FRAMING, REPLACE TO MATCH EXISTING

4 WINDOW NO. 209D
ROOM 209



IMAGE_ST201A

WINDOW TYPE


EXISTING GLAZING INVENTORY LEGEND

H= HISTORIC SUITABLE FOR REUSE
B= BROKEN UNSUITABLE FOR REUSE
IN THIS LOCATION (SEE GENERAL NOTES)

NOTES

- EXISTING WOOD WINDOW SASH, SILL, CASING, ETC. COMPONENTS ARE IN GOOD TO FAIR CONDITION AND GENERALLY SUITED FOR RESTORATION AND REUSE UNLESS NOTED OTHERWISE.
- REMOVE AND DISPOSE OF VINES.
- WINDOW CAVING IN THE CENTER, SUSPECTED WOOD ROT. CONTRACTOR TO INVESTIGATE AND REPAIR DAMAGED AREAS TO RESTORE WINDOW TO ITS 1910-1915 CONDITION.

① WINDOW NO. ST 201A
ROOM 209



IMAGE_ST202A

WINDOW TYPE

EXISTING GLAZING INVENTORY LEGEND

H= HISTORIC SUITABLE FOR REUSE
B= BROKEN UNSUITABLE FOR REUSE
IN THIS LOCATION (SEE GENERAL NOTES)

NOTES

- EXISTING WOOD WINDOW SASH, SILL, CASING, ETC. COMPONENTS ARE IN GOOD TO FAIR CONDITION AND GENERALLY SUITED FOR RESTORATION AND REUSE UNLESS NOTED OTHERWISE.
- WINDOW CAVING IN THE CENTER, SUSPECTED WOOD ROT. CONTRACTOR TO INVESTIGATE AND REPAIR DAMAGED AREAS TO RESTORE WINDOW TO ITS 1910-1915 CONDITION.

② WINDOW NO. ST 202A
ROOM 209

NEW WORK NOTES

ALL NEW WORK NOTES SHALL BE CONSIDERED TYPICAL UNLESS NOTED OTHERWISE (U.N.O.)

- RESTORE EXISTING SILL AND REINSTALL.
- NOT USED
- NOT USED
- ROTTED STILE/RAIL IN LOCATION NOTED.
- RESTORE/REPLACE EXISTING WOOD APRON.
- REPLACE ROTTED RAIL MATCH EXISTING.
- REPAIR/REPLACE ROTTED SILL.
- SUSPECTED WATER DAMAGE IN JAMB CONFIRM CONDITION REPAIR/REPLACE BASED ON CONDITION SPLIT SILL REPLACE.
- SILL/SASH ROTTED, REPLACE.
- FURNISH AND INSTALL NEW P.T. WOOD SILL. MATCH DIMENSIONS OF EXISTING.
- REMOVE AND REPLACE EXISTING HEAD JAMB AND SILL FRAMING AGAINST EXISTING BRICK MASONRY W/ PRESSURE TREATED LUMBER. MATCH EXISTING DIMENSIONS OF WOOD FRAMES AND MATCH EXISTING JOINT DETAILS.
- STRAIGHTEN AND LEVEL WINDOW SILL ACROSS FULL LENGTH OF WINDOW ASSEMBLY.
- MISSING APRON. INSTALL NEW APRON TO MATCH EXISTING
- REPAIR/REPLACE MULLION TO MATCH EXISTING.
- REPLACE MISSING TRIM TO MATCH EXISTING (SEE GENERAL NOTES)
- REPAIR AND SMOOTH MULLION TO MATCH EXISTING, READY FOR PAINT (SEE GENERAL NOTES)
- REPLACE ROTTED WINDOW CASING (SEE GENERAL NOTES)
- OPEN TO OUTSIDE, REPAIR AREA TO BE PROPERLY SEALED.
- REPLACE MISSING/DAMAGED CASING TO MATCH EXISTING (SEE GENERAL NOTES)
- REPAIR AND SMOOTH STILE/RAIL TO MATCH EXISTING, READY FOR PAINT (SEE GENERAL NOTES)
- REPAIR SAGGING/WARPED WOOD. STRAIGHTEN TO MATCH EXISTING.
- REPAIR/REPLACE ROTTED HEADER
- REPLACE ROTTED TRIM TO MATCH EXISTING (SEE GENERAL NOTES)
- REPAIR TRIM TO MATCH EXISTING, READY FOR PAINT (SEE GENERAL NOTES)
- REPAIR DAMAGED STOOL TO MATCH EXISTING



NOTE:
11"x17" SHEETS ARE PLOTTED AT 1/2 THE
SCALE NOTED ON THESE DRAWINGS.

**Florida Department of State
Division of Historical Resources**

**HISTORIC JEFFERSON
COUNTY HIGH SCHOOL
RESTORATION**

MONTEICELLO, FLORIDA

OWNER NAME:

**Jefferson County Board of
County Commissioners**

MONTEICELLO, FLORIDA

REV	DATE	DESCRIPTION
	04/20/2023	HURRICANE MICHAEL GRANT

PROJECT PHASE
100% CONSTRUCTION DOCUMENTS

DATE 01 AUGUST 2019	DRAWN BY RMP
PROJECT NO 65000	CHECKED BY SKCC

SHEET TITLE
WINDOW ANALYSIS

SHEET NO
A618

REV NO



ARCHITECTURE
PLANNING INTERIORS
GRAPHICS

ELLIOTT MARSHALL PINES PA, STATE LICENSE
251 E. 7TH AVENUE TALLAHASSEE FL 32303
(850) 222-7442
WWW.EMIAARCHITECTS.COM
LICENSE # 1A 030049 # 020153

NOTE:
11"x17" SHEETS ARE PLOTTED AT 1/2 THE
SCALE NOTED ON THESE DRAWINGS.

Florida Department of State
Division of Historical Resources

**HISTORIC JEFFERSON
COUNTY HIGH SCHOOL
RESTORATION**

MONTEICELLO, FLORIDA
OWNER NAME:
**Jefferson County Board of
County Commissioners**
MONTEICELLO, FLORIDA

REV	DATE	DESCRIPTION
1	04/20/2023	HURRICANE MICHAEL GRANT

PROJECT PHASE
100% CONSTRUCTION DOCUMENTS
DATE
01 AUGUST 2019
DRAWN BY
RMP
PROJECT NO
65000
CHECKED BY
SKCC

SHEET TITLE
FINISH SCHEDULE

SHEET NO
A620
REV NO
△

RM-NO	RM-NAME	FLR-FIN	BASE	N-FIN	E-FIN	S-FIN	W-FIN	CLG-FIN	CLG-HT	REMARKS
000	ELEC/MECH ROOM	SC-E	-	BPS-1	BPS-1	BPS-1	BPS-1	ES	-	
001	HOLDING CELL	SC-E	-	BPE-1	BPE-1	BPE-1	BPE-1	GPE	10'-6"	
002	HOLDING CELL	SC-E	-	BPE-1	BPE-1	BPE-1	BPE-1	GPE	10'-6"	
003	HOLDING CELL	SC-E	-	BPE-1	BPE-1	BPS-1	BPS-1	GPE	10'-6"	
004	RESTROOM	SC-E	-	BPS-1	BPS-1	BPS-1	BPS-1	ES	-	
005	MECHANICAL ROOM	SC-E	-	BPS-1	BPS-1	BPS-1	BPS-1	ES	-	
006	TELECOMMUNICATION ROOM	SC-E	-	BPE-1	BPS-1	BPE-1	BPE-1	ES	-	
007	MECHANICAL ROOM	SC-E	-	BPE-1	BPS-1	BPS-1	BPS-1	ES	-	
ST 001	WEST STAIR	-	-	BPE-1	BPS-1	BPE-1	-	ES	-	
ST 002	EAST STAIR	-	-	BPE-1	-	BPE-1	BPS-1	ES	-	

RM-NO	RM-NAME	FLR-FIN	BASE	N-FIN	E-FIN	S-FIN	W-FIN	CLG-FIN	CLG-HT	REMARKS
101	WOMEN'S RESTROOM	PT-1	PB-1	GP-1	GP-1	GP-1	GP-1	GPE	12'-2"	1
101A	CLOSET	PT-1	PB-1	GP-1	GP-1	GP-1	GP-1	GPE	10'-0"	-
102	MEN'S RESTROOM	PT-1	PB-1	GP-1	GP-1	GP-1	GP-1	GPE	12'-2"	5
102A	HALLWAY	WD-1	WB-1	GP-1	GP-1	GP-1	GP-1	GPE	12'-2"	5
103	EXHIBIT ROOM	WD-1	WB-1	GP-1	GP-1	GP-1	GP-1	WD-1	12'-2"	1
104	EXHIBIT ROOM	WD-1	WB-1	GP-1	GP-1	GP-1	GP-1	WD-1	12'-2"	1
105	EXHIBIT ROOM	WD-1	WB-1	GP-1	GP-1	GP-1	GP-1	WD-1	12'-2"	1
106	EXHIBIT ROOM	WD-1	WB-1	GP-1	GP-1	GP-1	GP-1	WD-1	12'-2"	1
107	EXHIBIT ROOM	WD-1	WB-1	GP-1	GP-1	GP-1	GP-1	WD-1	12'-2"	1
108	SECURITY ROOM	WD-1	WB-1	GP-1	GP-1	GP-1	GP-1	WD-1	12'-2"	1
109	ENTRY/FOYER	WD-1	WB-1	GP-1, BR	GP-1	GP-1	GP-1	WD-1	12'-2"	4
110	RECEPTION/WAITING ROOM	WD-1	WB-1	GP-1	GP-1	GP-1	GP-1	WD-1	12'-2"	5
111	OFFICE	WD-1	WB-1	GP-1	GP-1	GP-1	GP-1	WD-1	12'-2"	1
112	STORAGE	WD-1	WB-1	GP-1	GP-1	GP-1	GP-1	GP-1	12'-2"	5
113	OFFICE	WD-1	WB-1	GP-1	GP-1	GP-1	GP-1	WD-1	12'-2"	1
114	HALLWAY	WD-1	WB-1	GP-1	GP-1	GP-1	GP-1	WD-1	12'-2"	5
115	OFFICE	WD-1	WB-1	GP-1	GP-1	GP-1	GP-1	GP-1	12'-2"	1
116	KITCHENETTE	WD-1	WB-1	GP-1	GP-1	GP-1	GP-1	GP-1	12'-2"	1
EL101	ELEVATOR	-	-	-	-	-	-	-	-	
ST101	WEST STAIR	-	-	-	-	-	-	-	-	
ST102	EAST STAIR	WD-1	WB-1	GP-1	GP-1	GP-1	GP-1	WD-1	-	3

RM-NO	RM-NAME	FLR-FIN	BASE	N-FIN	E-FIN	S-FIN	W-FIN	CLG-FIN	CLG-HT	REMARKS
201	JURY ROOM	WD-1	WB-1	GP-1	GP-1	GP-1	GP-1	GP-1	11'-7"	1
202	RESTROOM	PT-1	PB-1	GP-1	GP-1	GP-1	GP-1	GPE	11'-7"	5
203	BAILIFF	WD-1	WB-1	GP-1	GP-1	GP-1	GP-1	GP-1	11'-7"	5
204	HALLWAY	WD-1	WB-1	GP-1	GP-1	GP-1	GP-1	GP-1	11'-7"	5
205	JUDICIAL ASSISTANT	WD-1	WB-1	GP-1	GP-1	GP-1	GP-1	GP-1	11'-7"	1
206	JUDGE'S CHAMBERS	WD-1	WB-1	GP-1	GP-1	GP-1	GP-1	GP-1	11'-7"	1
207	EXHIBIT ROOM	WD-1	WB-1	GP-1	GP-1	GP-1	GP-1	WD-1	11'-7"	1
208	EXHIBIT ROOM	WD-1	WB-1	GP-1	GP-1	GP-1	GP-1	WD-1	11'-7"	1
209	EXHIBIT ROOM	WD-1	WB-1	GP-1	GP-1	GP-1	GP-1	WD-1	11'-7"	1
ST201	WEST STAIR	-	-	-	-	-	-	-	-	
ST202	EAST STAIR	WD-1	WB-1	GP-1	GP-1	GP-1	GP-1	WD-1	-	

SYM	SURFACE	DEFINITION
PT	FLOOR	PORCELAIN TILE
CPT	FLOOR	CARPET, CLASS B CERTIFICATE REQUIRED
SC	FLOOR	CONCRETE, WITH PENETRATING STAIN AND SEALED
VCT	FLOOR	VINYL COMPOSITION TILE
CT	FLOOR	CERAMIC TILE
SC-E	FLOOR	CONCRETE, WITH PENETRATING STAIN AND SEALED W/ EPOXY
TZ	FLOOR	TERAZZO
WD	FLOOR	WOOD FLOOR
RC	BASE	RUBBER COVERED BASE
CT	BASE	CERAMIC TILE COVERED BASE
PB	BASE	PORCELAIN TILE BASE
WB	BASE	WOOD BASE
TZ	BASE	TERAZZO BASE
AWP	WALL	ACOUSTICAL WALL PANEL
CT	WALL	GLAZED CERAMIC TILE
BP	WALL	EXPOSED CONCRETE MASONRY UNITS, PAINTED
BPE	WALL	EXPOSED CONCRETE MASONRY UNITS, PAINTED WITH EPOXY (REFER TO 09 96 56)
BPS	WALL	EXPOSED CONCRETE MASONRY UNITS, PAINTED WITH SEALANT (THOROSEAL)
BR	WALL	EXPOSED BRICK MASONRY UNITS
ES	WALL	EXPOSED STRUCTURE
GPE	WALL	GYPSPUM WALL BOARD, PAINTED WITH EPOXY (REFER TO 09 96 56)
GP	WALL	GYPSPUM WALL BOARD, PAINTED
YWC	WALL	VINYL WALL COVERING
FWC	WALL	FABRIC WALL COVERING
ACT	CEILING	ACOUSTICAL CEILING TILE
ES	CEILING	EXPOSED STRUCTURE
ESP	CEILING	NO CEILING, PAINT EXPOSED STRUCTURE
EK	CEILING	EXISTING
GBP	CEILING	GYPSPUM BOARD PANELS
GP	CEILING	GYPSPUM WALLBOARD, PAINTED
GPE	CEILING	GYPSPUM WALLBOARD PAINTED W/ EPOXY (REFER TO 09 96 56)
WD	CEILING	WD CEILING

1. CEILING HEIGHT IS DETERMINED BY TOP OF WINDOW CASING. CONTRACTOR TO VERIFY HEIGHT OF CASING.
2. SEE SHEETS A130-A132 FOR REFLECTED CEILING PLANS AND DETAILS.
3. WOOD CEILING IS THE UNDERSIDE OF THE STAIR, AND FOLLOWS THE SLOPE OF THE STAIR.
4. SEE SHEET A701-A706-INTERIOR ELEVATIONS FOR HEIGHT OF WAINSCOTING AND EXPOSED BRICK WALL LOCATIONS.
5. WHERE WINDOWS ARE NOT IN ROOM MATCH CEILING HEIGHT TO ADJACENT ROOM.

A. EPOXY PAINT IS SPECIFIED AS A SPECIAL COATING.
B. SEE INTERIOR ELEVATION SHEETS A701-A706 AND MILLWORK DETAILS A710-A711 FOR CASEWORK FINISHES.
C. PAINT ACCESS DOORS TO MATCH COLOR OF ADJACENT WALL OR WAINSCOTING.

WINDOWS	MATCH EXISTING
DOORS	ARCHITECT TO SELECT
DOOR FRAMES	ARCHITECT TO SELECT
EXTERIOR BRICK PAVERS	SEE SPECIFICATIONS
SOUTH WOOD COLUMNS	MATCH EXISTING
CORNICE AND PILASTER ENTRY	MATCH EXISTING
PILASTER PARAPET	MATCH EXISTING
NORTH CONCRETE COLUMNS	MATCH EXISTING
EXTERIOR SOFFITS (NORTH + SOUTH)	MATCH EXISTING
CORNICE, FREIZE, ARCHITRAVE, AND PEDIMENT	MATCH EXISTING
ENTRY STAIRS (NORTH, EAST, WEST)	-----

MATERIAL	MANUFACTURER	STYLE	COLOR	COLOR NO
PAINT				
P-1 (FIELD)	BENJAMIN MOORE	INTERIOR READY-MIXED	BONE WHITE	PM-30
P-2 (TRIM, CASING, DOOR)	BENJAMIN MOORE	INTERIOR READY-MIXED	MATCH EXISTING	
PORCELAIN TILE				
PT-1 (12 X 24)	TRINITY TILE	URBAN	PORTLAND	-
PB-1 (4 X 12) - BASE	TRINITY TILE	URBAN	PORTLAND	-
CERAMIC TILE GROUT				
G-1	LATICRETE INTERNATIONAL	CLASSIC (GROUP 1)	ARCHITECT TO SELECT	-
WOOD BASE				
WB-1	--	MATCH EXISTING		-
WOOD FLOOR				
WD-1	GOODWIN COMPANY	HEART PINE		-
WOOD CEILING				
WD-1	GOODWIN COMPANY	HEART PINE		-
ACOUSTICAL WALL PANEL				
AWP-1	ACOUSTICAL SERVICES, INC	ACOUSTICORE 519		-
TOILET PARTITIONS				
	BOBRICK	DURALNESERIES 1080/1180	ARCHITECT TO SELECT	-

H
G
F
E
D
C
B
A

1

1

1

1

1

NOTE:
11"x17" SHEETS ARE PLOTTED AT 1/2 THE
SCALE NOTED ON THESE DRAWINGS.

Florida Department of State
Division of Historical Resources

**HISTORIC JEFFERSON
COUNTY HIGH SCHOOL
RESTORATION**

MONTEICELLO, FLORIDA

OWNER NAME:
**Jefferson County Board of
County Commissioners**

MONTEICELLO, FLORIDA

REV	DATE	DESCRIPTION

PROJECT PHASE
100% CONSTRUCTION DOCUMENTS

DATE
01 AUGUST 2019

DRAWN BY
RMP


PROJECT NO
65000

CHECKED BY
SKC

SHEET TITLE
**INTERIOR ELEVATIONS
2ND FLOOR**

SHEET NO
A703





REV NO



H
G
F
E
D
C
B
A

1 2 3 4 5 6 7 8 9

NOTE:
11"x17" SHEETS ARE PLOTTED AT 1/2 THE
SCALE NOTED ON THESE DRAWINGS.



Florida Department of State
Division of Historical Resources

**HISTORIC JEFFERSON
COUNTY HIGH SCHOOL
RESTORATION**

MONTICELLO, FLORIDA

OWNER NAME:
**Jefferson County Board of
County Commissioners**

MONTICELLO, FLORIDA

REV	DATE	DESCRIPTION

PROJECT PHASE
100% CONSTRUCTION DOCUMENTS

DATE 01 AUGUST 2019	DRAWN BY RMP
PROJECT NO 65000	CHECKED BY SKC


SHEET TITLE
**INTERIOR ELEVATIONS
2ND FLOOR**

SHEET NO A704	REV NO
-------------------------	--------


H
G
F
E
D
C
B
A

1 2 3 4 5 6 7 8 9

NOTE:
11"x17" SHEETS ARE PLOTTED AT 1/2 THE
SCALE NOTED ON THESE DRAWINGS.



1 ROOM 207
A705 EAST



2 ROOM 207
A705 SOUTH

Florida Department of State
Division of Historical Resources

**HISTORIC JEFFERSON
COUNTY HIGH SCHOOL
RESTORATION**

MONTICELLO, FLORIDA

OWNER NAME:
**Jefferson County Board of
County Commissioners**

MONTICELLO, FLORIDA

REV	DATE	DESCRIPTION


PROJECT PHASE
100% CONSTRUCTION DOCUMENTS

DATE 01 AUGUST 2019	DRAWN BY RMP
PROJECT NO 65000	CHECKED BY SKC


SHEET TITLE
**INTERIOR ELEVATIONS
2ND FLOOR**

SHEET NO A705	REV NO
-------------------------	--------


NOTE:
11"x17" SHEETS ARE PLOTTED AT 1/2 THE
SCALE NOTED ON THESE DRAWINGS.




1 ROOM 208 AND 105
A706 NORTH




2 ROOM 208 AND 105
A706 SOUTH




3 ROOM 208 AND 105
A706 EAST




4 ROOM 208 AND 105
A706 WEST




5 ROOM 209 AND 106
A706 NORTH




6 ROOM 209 AND 106
A706 SOUTH



7 ROOM 209 AND 106
A706 EAST



8 ROOM 209 AND 106
A706 WEST



Florida Department of State
Division of Historical Resources

**HISTORIC JEFFERSON
COUNTY HIGH SCHOOL
RESTORATION**

MONTECELLO, FLORIDA

OWNER NAME:
**Jefferson County Board of
County Commissioners**
MONTECELLO, FLORIDA

REV	DATE	DESCRIPTION
△	04/20/2023	HURRICANE MICHAEL GRANT

PROJECT PHASE
100% CONSTRUCTION DOCUMENTS

DATE
01 AUGUST 2019

DRAWN BY
RMP

PROJECT NO
65000

CHECKED BY
SKCC










SHEET TITLE
**INTERIOR ELEVATIONS
2ND FLOOR**

SHEET NO
A706

REV NO
△

H
G
F
E
D
C
B
A

1 2 3 4 5 6 7 8 9



Florida Department of State
Division of Historical Resources

HISTORIC JEFFERSON COUNTY HIGH SCHOOL RESTORATION

JEFFERSON COUNTY BOARD OF COUNTY COMMISSIONERS

REV	DATE	DESCRIPTION

PROJECT PHASE
PHASE CONSTRUCTION DOCUMENTS










DATE: 01 AUGUST 2019 DRAWN BY: AAU

PROJECT NO: 19000 CHECKED BY: SHC

SHEET TITLE
MILLWORK DETAILS

SHEET NO: **A711** REV NO:

NOTE:
11"x17" SHEETS ARE PLOTTED AT 1/2 THE
SCALE NOTED ON THESE DRAWINGS.



Florida Department of State
Division of Historical Resources

**HISTORIC JEFFERSON
COUNTY HIGH SCHOOL
RESTORATION**

MONTICELLO, FLORIDA
OWNER NAME:
**Jefferson County Board of
County Commissioners**
MONTICELLO, FLORIDA

REV	DATE	DESCRIPTION

PROJECT PHASE
100% CONSTRUCTION DOCUMENTS
DATE
01 AUGUST 2019
DRAWN BY
AAU
PROJECT NO
65000
CHECKED BY
SKCC

CEILING DETAILS

SHEET NO
A720
REV NO

NOTE:
11"x17" SHEETS ARE PLOTTED AT 1/2" THE SCALE NOTED ON THESE DRAWINGS.

HISTORIC JEFFERSON COUNTY HIGH SCHOOL RESTORATION

MONTEICELLO, FLORIDA

OWNER NAME:
Jefferson County Board of County Commissioners
MONTEICELLO, FLORIDA

REV	DATE	DESCRIPTION

PROJECT PHASE
100% CONSTRUCTION DOCUMENTS

DATE 01 AUGUST 2019 DRAWN BY RMP

PROJECT NO 65000 CHECKED BY SKC

SHEET TITLE

SIGNAGE SCHEDULE



SHEET NO **A801** REV NO

SIGN SCHEDULE - BASEMENT																			
NO.	SPACE	SIGN TYPE													QTY	LOCATION			
		A	B	C	D	E	F	G	H	J	K	L	M	N					
000	ELEC/MECH ROOM																	1	AT BASEMENT STAIR LANDING
001	HOLDING CELL																	1	ADJACENT TO DOOR # 001
002	HOLDING CELL																	1	ADJACENT TO DOOR # 002
003	HOLDING CELL																	1	ADJACENT TO DOOR # 003
004	CUSTODIAL ROOM																	1	ADJACENT TO DOOR # 004
005	MECHANICAL ROOM																	1	AT BASEMENT STAIR LANDING
006	TELECOMMUNICATION ROOM																	1	ADJACENT TO DOOR # 006
007	MECHANICAL ROOM																	1	AT BASEMENT STAIR LANDING
EL 001	ELEVATOR																	1	ADJACENT TO ELEVATOR DOOR
ST 001	WEST STAIR																	1	ADJACENT TO ELEVATOR DOOR
ST 002	EAST STAIR																	1	ADJACENT TO ELEVATOR DOOR


SIGN SCHEDULE - FIRST FLOOR																			
NO.	SPACE	SIGN TYPE													QTY	LOCATION			
		A	B	C	D	E	F	G	H	J	K	L	M	N					
101	WOMEN'S RESTROOM																	1	ADJACENT TO DOOR # 101
101A	CLOSET																	1	ADJACENT TO DOOR # 101
102	MEN'S RESTROOM																	1	ADJACENT TO DOOR # 102
102A	HALLWAY																	1	ADJACENT TO DOOR # 102
103	EXHIBIT ROOM																	1	ADJACENT TO DOOR # 103
104	EXHIBIT ROOM																	1	ADJACENT TO DOOR # 104
105	EXHIBIT ROOM																	1	ADJACENT TO DOOR # 105
106	EXHIBIT ROOM																	1	ADJACENT TO DOOR # 106
107	BUSINESS CENTER																	1	ADJACENT TO DOOR # 107
108	SECURITY ROOM																	1	ADJACENT TO DOOR # 108
109	ENTRY/FOYER																	2	ADJACENT TO DOOR # DR-A AND DR-B
110	RECEPTION/WAITING ROOM																	1	ADJACENT TO DOOR #
111	OFFICE																	1	ADJACENT TO DOOR # 111
112	STORAGE																	1	ADJACENT TO DOOR # 112
113	OFFICE																	1	ADJACENT TO DOOR # 113
114	HALLWAY																	1	ADJACENT TO DOOR # 114
115	OFFICE																	1	ADJACENT TO DOOR # 115
116	KITCHENETTE																	1	ADJACENT TO DOOR # 116
EL101	ELEVATOR																	1	ADJACENT TO ELEVATOR DOOR
ST101	WEST STAIR																	1	ADJACENT TO DOOR # DR-D
ST102	EAST STAIR																	1	ADJACENT TO DOOR # DR-C

SIGN SCHEDULE - SECOND FLOOR																			
NO.	SPACE	SIGN TYPE													QTY	LOCATION			
		A	B	C	D	E	F	G	H	J	K	L	M	N					
201	JURY ROOM																	1	ADJACENT TO DOOR # 201
202	RESTROOM																	1	ADJACENT TO DOOR # 202
203	BALIFF																	1	ADJACENT TO DOOR # 203
204	HALLWAY																	1	ADJACENT TO DOOR # 204
205	JUDICIAL ASSISTANT																	1	ADJACENT TO DOOR # 205
206	JUDGE'S CHAMBERS																	1	ADJACENT TO DOOR # 206
207	MEETING/COURTROOM																	2	ADJACENT TO DOOR # 207
208	EXHIBIT ROOM																	1	ADJACENT TO DOOR # 208
209	EXHIBIT ROOM																	1	ADJACENT TO DOOR # 209
EL201	ELEVATOR																	1	ADJACENT TO ELEVATOR DOOR
ST201	WEST STAIR																	1	ADJACENT TO ELEVATOR DOOR
ST202	EAST STAIR																	1	ADJACENT TO ELEVATOR DOOR


- SIGN SCHEDULE NOTES**
- VERIFY ROOM NAMES, NUMBERS AND LOCATION WITH OWNER BEFORE PROCEEDING WITH FABRICATION.
 - PLACEMENT OF SIGNS SHALL BE COORDINATED IN THE FIELD WITH THE ARCHITECT.
 - EXTERIOR SIGNS SHALL BE UV RESISTANT.
 - WHERE SIGNS OCCUR ON A GLASS PANEL, PROVIDE A PLAIN PANEL TO MATCH SIGN COLOR ON THE OPPOSITE SIDE OF THE GLASS.




ROOM NUMBER (SEE SCHEDULE)
CORNERS: 1/2" RADIUS (TYP)
LETTERS AND NUMERALS RAISED 1/32", UPPER CASE, SANS SERIF OR SIMPLE SERIF TYPE (TYP)
ROOM NAME (SEE SCHEDULE)
GRADE 2 BRAILLE CHARACTERS (TYP) (BRAILLE TAPE NOT ACCEPTABLE)




CORNERS: 1/2" RADIUS (TYP)
LETTERS AND NUMERALS RAISED 1/32", UPPER CASE, SANS SERIF OR SIMPLE SERIF TYPE (TYP)
GRADE 2 BRAILLE CHARACTERS (TYP) (BRAILLE TAPE NOT ACCEPTABLE)
OCCUPANCY: LOBBY 101 = 152 PERSONS (2278 NSF/15 NSF)




LETTERS AND NUMERALS RAISED 1/32", UPPER CASE, SANS SERIF OR SIMPLE SERIF TYPE (TYP)
CORNERS: 1/2" RADIUS (TYP)
GRADE 2 BRAILLE CHARACTERS (TYP) (BRAILLE TAPE NOT ACCEPTABLE)




CORNERS: 1/2" RADIUS (TYP)
INTERNATIONAL ACCESSIBILITY SYMBOL
LETTERS AND NUMERALS RAISED 1/32", UPPER CASE, SANS SERIF OR SIMPLE SERIF TYPE (TYP)
GRADE 2 BRAILLE CHARACTERS (TYP) (BRAILLE TAPE NOT ACCEPTABLE)
BRAILLE MUST INDICATE THAT ROOM IS ACCESSIBLE TO THE DISABLED.




WALL MOUNTED RESTROOM IDENTIFICATION SIGN WITH ROOM NUMBER, INTERNATIONAL ACCESSIBILITY SYMBOL AND MALE AND FEMALE LOGO. RAISED LETTERS MUST BE ACCOMPANIED BY GRADE 2 BRAILLE.




LETTERS AND NUMERALS RAISED 1/32", UPPER CASE, SANS SERIF OR SIMPLE SERIF TYPE (TYP)
SERIF TYPE (TYP.)
GRADE 2 BRAILLE CHARACTERS (TYP.) (BRAILLE TAPE NOT ACCEPTABLE)




ADJACENT TO ELEVATOR ON EACH LEVEL
CORNERS: 1/2" RADIUS (TYP)
LETTERS AND NUMERALS RAISED 1/32", UPPER CASE, SANS SERIF OR SIMPLE SERIF TYPE (TYP)
GRADE 2 BRAILLE CHARACTERS (TYP) (BRAILLE TAPE NOT ACCEPTABLE)
VISIBLE WIDTH




CORNERS: 1/2" RADIUS (TYP)
LETTERS AND NUMERALS RAISED 1/32", UPPER CASE, SANS SERIF OR SIMPLE SERIF TYPE (TYP)
GRADE 2 BRAILLE CHARACTERS (TYP) (BRAILLE TAPE NOT ACCEPTABLE)



CORNERS: 1/2" RADIUS (TYP)
LETTERS AND NUMERALS RAISED 1/32", UPPER CASE, SANS SERIF OR SIMPLE SERIF TYPE (TYP)
WALL MOUNTED, UV RESISTANT EXTERIOR SIGN. BACKGROUND COLOR OF SIGN TO BE RED AND LETTERS ARE TO BE WHITE. RAISED LETTERS MUST BE ACCOMPANIED WITH GRADE 2 BRAILLE.




ROOM NUMBER (SEE SCHEDULE)
CORNERS: 1/2" RADIUS (TYP)
LETTERS AND NUMERALS RAISED 1/32", UPPER CASE, SANS SERIF OR SIMPLE SERIF TYPE (TYP)
ROOM NAME (SEE SCHEDULE)
GRADE 2 BRAILLE CHARACTERS (TYP) (BRAILLE TAPE NOT ACCEPTABLE)



CORNERS: 1/2" RADIUS (TYP)
CLEAR WINDOW FOR FLOOR PLAN DIAGRAM (PRINTED INSERT)
LETTERS AND NUMERALS RAISED 1/32", UPPER CASE, SANS SERIF OR SIMPLE SERIF TYPE (TYP)
GRADE 2 BRAILLE CHARACTERS (TYP) (BRAILLE TAPE NOT ACCEPTABLE)
WALL MOUNTED SIGN WITH PRIMARY AND SECONDARY EVACUATION ROUTES INDICATED BY CONTRASTING COLORS AND NUMBERS. MOUNT SIGN ADJACENT TO THE PRIMARY EXIT DOOR FROM EACH STUDENT-OCCUPIED SPACE. RAISED LETTERS MUST BE ACCOMPANIED WITH GRADE 2 BRAILLE.

NOTE:
11"x17" SHEETS ARE PLOTTED
AT 1/2 THE SCALE NOTED ON
THESE DRAWINGS.



r.e. Walsh Engineering, Inc.
3073 Hickory Wind Road, Tallahassee, Florida 32317
Phone (850) 656-3800 C.A.#00009540

This item has been digitally signed and sealed by Roger E. Walsh, P.E. on the indicated date using a Digital Signature. Printed copies of this document are not considered signed and sealed and the signature must be verified on any electronic copies.

Roger E. Walsh, P.E.
FLA #36997

**Florida Department of State
Division of Historical Resources**

HISTORIC JEFFERSON COUNTY HIGH SCHOOL RESTORATION

MONTECELLO, FLORIDA

OWNER NAME:
**Jefferson County Board of
County Commissioners**
MONTECELLO, FLORIDA

REV	DATE	DESCRIPTION


PROJECT PHASE
100% CONSTRUCTION DOCUMENTS

DATE: 01 AUGUST 2019 DRAWN BY: REW


PROJECT NO: 65000 CHECKED BY: REW

SHEET TITLE **PLUMBING SCHEDULE, LEGEND AND PLUMBING DETAILS**


SHEET NO: **P101** REV NO:



ELECTRIC WATER HEATER DETAIL
SCALE: NONE



HUB DRAIN DETAIL
SCALE: NONE



RECIRCULATION PUMP WIRING
SCALE: NONE


- ### GENERAL NOTES
- SEE ARCHITECTURAL DRAWINGS FOR BUILDING DIMENSIONS AND DETAILS. THESE PLUMBING DRAWINGS ARE DIAGRAMMATIC ONLY AND ARE NOT INTENDED TO BE SCALED.
 - REFER TO EQUIPMENT LAYOUT PLANS FOR SPECIFIC PLACEMENT OF EQUIPMENT AND DRAINS.
 - COORDINATE PIPE ROUTING AND EQUIPMENT LOCATIONS WITH HVAC AND ELECTRICAL INSTALLATIONS AND WITH BUILDING STRUCTURAL MEMBERS. CONFLICTING WORK NOT COORDINATED WILL BE REMOVED TO THE EXTENT NECESSARY TO ALLOW PROPER INSTALLATION OF ALL SYSTEMS.
 - REFER TO ELECTRICAL DRAWINGS FOR VOLTAGE AND PHASE REQUIREMENTS OF ALL EQUIPMENT.
 - SUPPORT ALL PIPING AND EQUIPMENT FROM PRIMARY BUILDING STRUCTURAL MEMBERS ONLY.
 - ALL CONSTRUCTION SHALL COMPLY WITH THE FLORIDA BUILDING CODE, 6TH ED.

FIXTURE CONNECTION SCHEDULE


MARK	FIXTURE	RIM HEIGHT	COLD WATER		HOT WATER		SOIL/WASTE	
			BRANCH	CONN.	BRANCH	CONN.	BRANCH	CONN.
P1	SECURITY COMBO 1		1" & 1/2"	1" & 1/2"	1/2"	1/2"	4" & 2"	3" & 1 1/2"
P2	SECURITY COMBO 2		1" & 1/2"	1" & 1/2"	1/2"	1/2"	4" & 2"	3" & 1 1/2"
P3	WATER CLOSET (ADA)	18"	1"	1"	--	--	4"	4"
P4	WATER CLOSET	15"	1"	1"	--	--	4"	4"
P5	LAVATORY (H.C.)	34"	1/2"	3/8"	1/2"	3/8"	2"	1 1/4"
P6	URINAL	24"	1"	1"	--	--	4"	4"
P6A	URINAL	17"	1"	1"	--	--	4"	4"
P7	MOP SINK		1/2"	3/8"	1/2"	3/8"	2"	2"
P8	DBL BASIN SS SINK		1/2"	3/8"	1/2"	3/8"	2"	2"

PLUMBING LEGEND



---	EXIST. WASTE PIPING
- - - - -	EXIST. VENT PIPING
---	EXIST. COLD WATER PIPING
---	EXIST. HOT WATER PIPING
---	EXISTING. HOT WATER RECIRCULATION PIPING
---	NEW WASTE PIPING
- - - - -	NEW VENT PIPING
---	NEW COLD WATER PIPING
---	NEW HOT WATER PIPING
DFU	DRAINAGE FIXTURE UNITS
WSFU	WATER SUPPLY FIXTURE UNITS
WV	WET VET
VTR	VENT THRU ROOF
V	VENT
H.B.	HOSE BIBB
C.O.	CLEAN OUT



ELEVATOR SUMP PUMP DETAIL
NOT TO SCALE





WATER PRESSURE REDUCTION DETAIL
SCALE: NONE



EXISTING BASEMENT PLUMBING ROUGH-IN PLAN

SCALE: 1/8" = 1'-0"



COMPLETED BASEMENT PLUMBING PLAN

SCALE: 1/8" = 1'-0"

NEW WORK NOTES:

THIS SHEET ONLY


- ① TIE INTO EXISTING 2" STUB IN BASEMENT AND EXTEND TO WATER UTILITY. REFER TO CIVIL SITE UTILITIES PLAN FOR CONTINUATION. PROVIDE PRESSURE REDUCING STATION AT BUILDING ENTRY AS DETAILED.
- ② INSTALL 2-WAY CLEAN OUT AND EXTEND BUILDING DRAIN TO SEWER UTILITY. REFER TO CIVIL SITE UTILITIES PLAN FOR CONTINUATION.
- ③ PROVIDE AND PLUMB WATER HEATER AS DETAILED.
- ④ INSTALL FULL BORE ISOLATION VALVES.
- ⑤ PROVIDE AND INSTALL FLOOR DRAINS AT ROUGH-IN LOCATIONS. TYPICAL.
- ⑥ PROVIDE AND INSTALL ALL PLUMBING FIXTURES WITH ALL NECESSARY APPURTENANCES FOR A COMPLETE AND OPERABLE INSTALLATION. ALL PLUMBING FIXTURES RECEIVING HOT WATER EXCEPT MOP SINKS SHALL BE PROVIDED WITH A TEMPERING VALVE TO REDUCE WATER TEMPERATURE AT DISCHARGE TO 110F.
- ⑦ TIE VENT INTO EXISTING 2" VENT STUB OUT HERE.
- ⑧ SAW CUT FLOOR AS NEEDED TO ALLOW FOR EXTENSION OF BUILDING DRAIN AS INDICATED.
- ⑨ OFFSET BUILDING DRAIN TO BRING STACK OUT OF WALL PLANE.
- ⑩ EXTEND HOT AND COLD PIPING EXPOSED IN ROOM P004 TO FIXTURES P1 AND P7 ON BASEMENT LEVEL AND UP TO P8 ON 1ST FLOOR LEVEL CONCEALED IN WALL. PROVIDE FULL BORE BALL VALVE FOR FIXTURES P1 AND P7 EXPOSED IN ROOM 004 TO ACT AS SERVICE VALVES. FLUSH VALVE AND FAUCET CONTROLS EXPOSED IN ROOM 004.
- ⑪ TURN HOT AND COLD WATER PIPING DOWN EXPOSED ON WALL.
- ⑫ EXTEND HOT AND COLD WATER PIPING TO P2 FIXTURES. EXTEND NEW VENT PIPING AS INDICATED. FLUSH VALVE AND FAUCET CONTROLS EXPOSED IN CRAWL SPACE BELOW STAIRS.
- ⑬ PROVIDE A LIBERTY PUMP MODEL ELV280-5 COMPLETE SUMP PUMP SYSTEM DESIGNED SPECIFICALLY FOR ELEVATOR SUMP APPLICATIONS COMPLYING WITH ALL THE REQUIREMENTS OF ASTM A17.1. INSTALL CONTROL PANEL AND REMOTE ALARM IN ROOM 004. EXTEND ALL CONDUCTORS IN ACCORDANCE WITH THE REQUIREMENTS OF THE ELECTRICAL SYSTEM SPECIFICATIONS.
- ⑭ 3" HUB DRAIN STUBBED UP IN CRAWL SPACE. PROVIDE TRANSITION FROM EXISTING HUB DRAIN PIPE SIZE TO 6" TO ACCEPT DISCHARGE FROM ELEVATOR PUMP SUMP AND CONDENSATE DRAIN.
- ⑮ EXTEND 1-1/2" CPVC PUMP DISCHARGE IN ELEVATOR SHAFT. RISE TO 12" ABOVE HUB DRAIN ELEVATION, CORE DRILL TO CRAWL SPACE AND DISCHARGE INTO HUB DRAIN.
- ⑯ PROVIDE HUB DRAIN WITH TRAP EXPOSED ABOVE FLOOR LEVEL, LOW AS POSSIBLE. CORE DRILL THROUGH WALL INTO CRAWLS SPACE. TRNECH IN CRAWL SPACE AND TIE INTO EXISTING HUB DRAIN LINE.
- ⑰ 1" MAKE-UP WATER LINE TO MECHANICAL EQUIPMENT YARD. TURN DOWN TO BELOW GRADE. REFER TO MECHANICAL SHEETS FOR CONTINUATION.



ARCHITECTURE
PLANNING INTERIORS
GRAPHICS

ELLIOTT MARSHALL JONES P.A. (E.M.J.)
251 E. 7TH AVENUE TALLAHASSEE FL 32303
(850) 222-7442
www.emjarch.com
SICRIP #1 AA-C09609 # C000153

NOTE:
11"x17" SHEETS ARE PLOTTED
AT 1/2 THE SCALE NOTED ON
THESE DRAWINGS.



r.e. Walsh Engineering, Inc.
3073 Hickory Wind Road, Tallahassee, Florida 32317
Phone (850) 656-3800 C.A.#00009540

This item has been digitally signed and sealed by
Roger E. Walsh, P.E. on the indicated date using a
Digital Signature. Printed copies of this document are
not considered signed and sealed and the signature
must be verified on any electronic copies.

Roger E. Walsh, P.E.
FLA #36997

Florida Department of State
Division of Historical Resources

**HISTORIC JEFFERSON
COUNTY HIGH SCHOOL
RESTORATION**

MONTECELLO, FLORIDA

OWNER NAME:
**Jefferson County Board of
County Commissioners**
MONTECELLO, FLORIDA

REV	DATE	DESCRIPTION


PROJECT PHASE
100% CONSTRUCTION DOCUMENTS

DATE 01 AUGUST 2019	DRAWN BY REW
PROJECT NO 65000	CHECKED BY REW

SHEET TITLE
**BASEMENT
PLUMBING PLAN**

SHEET NO P201	REV NO
-------------------------	--------

NOTE:
11"x17" SHEETS ARE PLOTTED
AT 1/2 THE SCALE NOTED ON
THESE DRAWINGS.



r.e. Walsh Engineering, Inc.
3073 Hickory Wind Road, Tallahassee, Florida 32317
Phone (850) 656-3800 C.A.#00009540

This item has been digitally signed and sealed by
Roger E. Walsh, P.E. on the indicated date using a
Digital Signature. Printed copies of this document are
not considered signed and sealed and the signature
must be verified on any electronic copies.

Roger E. Walsh, P.E.
FLA #36997

**Florida Department of State
Division of Historical Resources**

**HISTORIC JEFFERSON
COUNTY HIGH SCHOOL
RESTORATION**

MONTECELLO, FLORIDA
OWNER NAME:
**Jefferson County Board of
County Commissioners**
MONTECELLO, FLORIDA


REV	DATE	DESCRIPTION

PROJECT PHASE
100% CONSTRUCTION DOCUMENTS

DATE 01 AUGUST 2019	DRAWN BY REW
PROJECT NO 65000	CHECKED BY REW


SHEET TITLE
**FIRST FLOOR
PLUMBING PLAN**

SHEET NO P202	REV NO
-------------------------	--------



COMPLETED FIRST FLOOR PLUMBING PLAN
SCALE: 1/8" = 1'-0"

- NEW WORK NOTES:**
THIS SHEET ONLY
- ① TIE NEW 2" VENT INTO EXISTING RISER FOR P4 AND EXTEND TO EXISTING VENT AS INDICATED.
 - ② MODIFY RISER TO ACCOMMODATE TWO P5 FIXTURES IN THIS LOCATION.




EXISTING FIRST FLOOR PLUMBING ROUGH-IN PLAN
SCALE: 1/8" = 1'-0"

- DEMOLITION WORK NOTES:**
THIS SHEET ONLY
- ① DEMOLISH PIPING TO RELOCATED LAVATORY.
 - ② MODIFY EXISTING ROUGH-IN FOR ONE LAVATORY TO ACCOMMODATE A SECOND LAVATORY.


H
G
F
E
D
C
B
A

1 2 3 4 5 6 7 8 9

H
G
F
E
D
C
B
A



 **EXISTING FIRST FLOOR PLUMBING ROUGH-IN PLAN**
SCALE: 1/8" = 1'-0"




 **COMPLETED SECOND FLOOR PLUMBING PLAN**
SCALE: 1/8" = 1'-0"

NEW WORK NOTES:
THIS SHEET ONLY
① EXTEND EXISTING VENT THROUGH ROOF.



ARCHITECTURE
PLANNING INTERIORS
GRAPHICS
ELLIOTT MARSHAL BONES P.A. (E.M.B.)
251 E. 7TH AVENUE TALLAHASSEE FL 32303
(850) 222-7442
www.emibones.com
SICRIF #1 AA-C09609 # C00153

NOTE:
11"x17" SHEETS ARE PLOTTED
AT 1/2 THE SCALE NOTED ON
THESE DRAWINGS.



r.e. Walsh Engineering, Inc.
3073 Hickory Wind Road, Tallahassee, Florida 32317
Phone (850) 656-3800 C.A. #00009540

This item has been digitally signed and sealed by
Roger E. Walsh, P.E. on the indicated date using a
Digital Signature. Printed copies of this document are
not considered signed and sealed and the signature
must be verified on any electronic copies.

Roger E. Walsh, P.E.
FLA #36997

Florida Department of State
Division of Historical Resources

**HISTORIC JEFFERSON
COUNTY HIGH SCHOOL
RESTORATION**
MONTICELLO, FLORIDA

OWNER NAME:
**Jefferson County Board of
County Commisssioners**
MONTICELLO, FLORIDA

REV	DATE	DESCRIPTION

PROJECT PHASE
100% CONSTRUCTION DOCUMENTS


DATE 01 AUGUST 2019	DRAWN BY REW
PROJECT NO 65000	CHECKED BY REW

SHEET TITLE
**SECOND FLOOR
PLUMBING PLAN**

SHEET NO P203	REV NO
-------------------------	--------

1 2 3 4 5 6 7 8 9

NOTE:
11"x17" SHEETS ARE PLOTTED
AT 1/2 THE SCALE NOTED ON
THESE DRAWINGS.



r.e. Walsh Engineering, Inc.
3073 Hickory Wind Road, Tallahassee, Florida 32317
Phone (850) 656-3800 C.A. #00009540

This item has been digitally signed and sealed by
Roger E. Walsh, P.E. on the indicated date using a
Digital Signature. Printed copies of this document are
not considered signed and sealed and the signature
must be verified on any electronic copies.

Roger E. Walsh, P.E.
FLA #36997

**Florida Department of State
Division of Historical Resources**

**HISTORIC JEFFERSON
COUNTY HIGH SCHOOL
RESTORATION**

MONTECELLO, FLORIDA

OWNER NAME:
**Jefferson County Board of
County Commissioners**
MONTECELLO, FLORIDA

REV	DATE	DESCRIPTION

PROJECT PHASE
100% CONSTRUCTION DOCUMENTS

DATE
01 AUGUST 2019

DRAWN BY
REW

PROJECT NO
65000


CHECKED BY
REW

SHEET TITLE

PLUMBING RISERS


SHEET NO
P301

REV NO



EXISTING ROUGH-IN DRAIN RISER
SCALE: NONE

DEMOLITION WORK NOTES:
THIS SHEET ONLY
1 DEMOLISH PIPING TO RELOCATED LAVATORY.




NEW COMPLETED DRAIN RISER
SCALE: NONE

NEW WORK NOTES:
THIS SHEET ONLY
1 PROVIDE AND INSTALL FLOOR DRAINS AT ROUGH-IN LOCATIONS. TYPICAL.
2 TIE VENT INTO EXISTING 2" VENT STUB OUT HERE.
3 SAW CUT FLOOR AS NEEDED TO ALLOW FOR EXTENSION OF BUILDING DRAIN AS INDICATED.
4 OFFSET BUILDING DRAIN TO BRING STACK OUT OF WALL PLANE.
5 TIE NEW 2" VENT INTO EXISTING RISER FOR P4 AND EXTEND TO EXISTING VENT AS INDICATED.
6 EXTEND VENT TO TIE INTO VENT THROUGH ROOF.
7 EXTEND VENT THROUGH ROOF NOT LESS THAN 48" FROM DRIP EDGE.
8 REPAIR APPROXIMATELY 16" SECTION OF REMOVED VENT.

H
G
F
E
D
C
B
A

1 2 3 4 5 6 7 8 9

NOTE:
11"x17" SHEETS ARE PLOTTED
AT 1/2 THE SCALE NOTED ON
THESE DRAWINGS.



r.e. Walsh Engineering, Inc.
3073 Hickory Wind Road, Tallahassee, Florida 32317
Phone (850) 656-3800 C.A.#00009540

This item has been digitally signed and sealed by
Roger E. Walsh, P.E. on the indicated date using a
Digital Signature. Printed copies of this document are
not considered signed and sealed and the signature
must be verified on any electronic copies.

Roger E. Walsh, P.E.
FLA #36997

**Florida Department of State
Division of Historical Resources**

**HISTORIC JEFFERSON
COUNTY HIGH SCHOOL
RESTORATION**
MONTICELLO, FLORIDA

OWNER NAME:
**Jefferson County Board of
County Commissioners**
MONTICELLO, FLORIDA


REV	DATE	DESCRIPTION

PROJECT PHASE
100% CONSTRUCTION DOCUMENTS

DATE 01 AUGUST 2019	DRAWN BY REW
PROJECT NO 65000	CHECKED BY REW


SHEET TITLE
PLUMBING RISERS

SHEET NO P302	REV NO
-------------------------	--------



DEMOLITION WORK NOTES:

THIS SHEET ONLY
1 DEMOLISH PIPING TO RELOCATED LAVATORY.



NEW WORK NOTES:

THIS SHEET ONLY
5 INSTALL FULL BORE ISOLATION VALVES.
2 MODIFY RISER TO ACCOMMODATE TWO P5 FIXTURES IN THIS LOCATION.
3 EXTEND HOT, COLD, AND RECIRCULATION PIPING TO NEW WATER HEATER AND PIPE AS DETAILED.
4 EXTEND HOT AND COLD PIPING TO NEW AS INDICATED.
5 PROVIDE WATER HAMMER ARRESTER WHERE INDICATED WITH ISOLATION COCK. WHERE CONCEALED, PROVIDE A KEY LOCKING STAINLESS STEEL 12X12 ACCESS DOOR.

FAN COIL UNITS																			
MARK	FAN DATA				COOLING COIL						HEATING COIL				Description	LOCATION	ENVIRO-TEC MODEL		
	Airflow	Motor HP (QTY)	Total Capacity	Sensible Capacity	EAT DB	EAT WB	LAT DB	LAT WB	Fluid Flow	Fluid PD	Sensible Capacity	AIR DT	HW GPM	Fluid PD					
FC-B1	282	(1) 1/4									11384	37	1.30	1.36	Vertical Floor Exposed Slope Top FCU	WALL	VFS-C-4		
FC-B2	207	(1) 1/4									12214	54	0.90	1.01	Horizontal Concealed Plenum Return FCU	SUSPENDED	HLP-D-2		
FC-B4	125	(1) 1/4	4.15	3.46	80	65	55.0	53.8	0.8	2.26	6251	45	0.6	0.29	Vertical Floor Exposed Slope Top FCU	WALL	VFS-C-2		
FC-B5	125	(1) 1/4	4.15	3.46	80	65	55.0	53.8	0.8	2.26	6251	45	0.6	0.29	Vertical Floor Exposed Slope Top FCU	WALL	VFS-C-2		
FC-B6	125	(1) 1/4	4.15	3.46	80	65	55.0	53.8	0.8	2.26	6251	45	0.6	0.29	Vertical Floor Exposed Slope Top FCU	WALL	VFS-C-2		
FC-11A	125	(1) 1/4	4.39	3.50	80	65	54.7	53.1	1.8	1.42	5144	37	0.5	0.23	Vertical Floor Concealed FCU	WALL	VFC-C-2		
FC-11B	125	(1) 1/4	4.39	3.50	80	65	54.7	53.1	1.8	1.42	5144	37	0.5	0.23	Vertical Floor Concealed FCU	WALL	VFC-C-2		
FC-11C	125	(1) 1/4	4.39	3.50	80	65	54.7	53.1	1.8	1.42	5144	37	0.5	0.23	Vertical Floor Concealed FCU	WALL	VFC-C-2		
FC-11D	125	(1) 1/4	4.39	3.50	80	65	54.7	53.1	1.8	1.42	5144	37	0.5	0.23	Vertical Floor Concealed FCU	WALL	VFC-C-2		
FC-12	602	(1) 1/4	21.25	16.39	80	65	55.4	53.0	7.6	7.12	23524	35	2.3	0.74	Vertical Floor Concealed FCU	WALL	VFC-C-2		
FC-13	115	(1) 1/4	3.72	3.18	80	65	55.0	54.1	1.2	0.66	5894	46	0.6	0.27	Vertical Floor Concealed FCU	WALL	VFC-C-2		
FC-14	214	(1) 1/4	9.71	7.16	80	65	49.8	49.0	3.0	4.46	12330	51	1.2	0.24	Vertical Floor Concealed FCU	WALL	VFC-C-6		
FC-15	214	(1) 1/4	9.71	7.16	80	65	49.8	49.0	3.0	4.46	12330	51	1.2	0.24	Vertical Floor Concealed FCU	WALL	VFC-C-6		
FC-16	488	(2) 1/4	18.98	14.53	80	65	53.1	51.6	5.0	4.37	24195	44	2.4	0.94	Vertical Floor Concealed FCU	WALL	VFC-C-10		
FC-17	488	(2) 1/4	18.98	14.53	80	65	53.1	51.6	5.0	4.37	24195	44	2.4	0.94	Vertical Floor Concealed FCU	WALL	VFC-C-10		
FC-18	802	(2) 1/4	28.69	22.20	80	65	55.0	52.9	8.5	5.47	34507	38	3.4	2.08	Vertical Floor Concealed FCU	WALL	VFC-C-12		
FC-19A	115	(1) 1/4	4.08	3.33	80	65	53.8	53.0	1.4	0.93	5894	46	0.6	0.27	Vertical Floor Concealed FCU	WALL	VFC-C-2		
FC-19B	115	(1) 1/4	4.65	3.57	80	65	52.0	51.1	2.0	1.58	5894	46	0.6	0.27	Vertical Floor Concealed FCU	WALL	VFC-C-2		
FC-21	802	(2) 1/4	29.19	22.43	80	65	54.7	52.6	9.2	6.33	34507	38	3.4	2.08	Vertical Floor Concealed FCU	WALL	VFC-C-12		
FC-22	115	(1) 1/4	4.08	3.33	80	65	53.8	53.0	1.4	0.93	5894	46	0.6	0.27	Vertical Floor Concealed FCU	WALL	VFC-C-2		
FC-23	488	(2) 1/4	18.98	14.53	80	65	53.1	51.6	5.0	4.37	24195	44	2.4	0.94	Vertical Floor Concealed FCU	WALL	VFC-C-10		
FC-24	488	(2) 1/4	18.98	14.53	80	65	53.1	51.6	5.0	4.37	24195	44	2.4	0.94	Vertical Floor Concealed FCU	WALL	VFC-C-10		
BC-B1	373	(1) 1/3	14.04	11.01	80	65	53.3	52.2	3.0	5.07	19226	47	1.9	3.43	Vertical High Performance FCU	WALL	CDV-4		
BC-11	911	(2) 1/3	39.29	29.69	80	65	50.6	50.0	7.7	5.44	54828	54	5.4	1.45	Vertical High Performance FCU	WALL	CDV-2D		
BC-21	1,000	(1) 1	33.80	27.80	80	65	54.9	53.7	7.4	2.78	55000	37	2.7	2.01	Horizontal Blower Coil	SUSPENDED	HDD-08		

LEGEND	
IN. WG	DUCT SIZE: FIRST DIMENSION IS SIDE DRAWN
CFM	INCHES WATER GAUGE
MBH	CUBIC FEET PER MINUTE
Ø	BTU/H X 1000
Ø	DIAMETER
A.F.F	ABOVE FINISHED FLOOR
OA	OUTDOOR AIR
=====	FLEXIBLE DUCT
-----	CONDENSATE DRAIN PIPING
-----	MANUAL DAMPER
ESP	EXTERNAL STATIC PRESSURE
⊙	WALL MOUNTED THERMOSTAT
⊙	GRILLE DESIGNATION
-----	CHILLED WATER SUPPLY PIPING
-----	CHILLED WATER RETURN PIPING
-----	HOT WATER SUPPLY PIPING
-----	HOT WATER RETURN PIPING

EXHAUST FANS						
MARK	CFM	APPROX EXT. SP IN W.G.	MOTOR WATTS	FAN RPM	MAX NOISE SONES	COOK MODEL
EF-B1	650	0.35	153	749	2.5	GN-822
EF-21	355	0.25	137	1400	1.3	GN-622

NOTES:
EGRAL SPEED CONTROLLER.
EGRAL DISCONNECT.
WFT DAMPER.

COIL CONNECTION AND CONTROL VALVE SCHEDULE																											
UNIT TAG	AHU-B1	ERU-1	FC-B1	FC-B2	FC-B4	FC-B5	FC-B6	FC-11A	FC-11B	FC-11C	FC-11D	FC-12	FC-13	FC-14	FC-15	FC-16	FC-17	FC-18	FC-19A	FC-19B	FC-21	FC-22	FC-23	FC-24	BC-B1	BC-11	BC-21
BRANCH PIPE SIZE	1-1/4"	2-1/2"	N/A	N/A	3/4"	3/4"	3/4"	3/4"	3/4"	3/4"	3/4"	1-1/4"	3/4"	3/4"	3/4"	1"	1"	1-1/4"	3/4"	3/4"	1-1/4"	3/4"	1"	1"	3/4"	1-1/4"	1-1/4"
VALVE CONFIGURATION	3-WAY	3-WAY	N/A	N/A	2-WAY	2-WAY	2-WAY	2-WAY	2-WAY	2-WAY	2-WAY	2-WAY	2-WAY	2-WAY	2-WAY	2-WAY	2-WAY	2-WAY	2-WAY	2-WAY	2-WAY	2-WAY	2-WAY	2-WAY	2-WAY	2-WAY	2-WAY
NORMAL TO COIL	CLOSED	CLOSED	N/A	N/A	CLOSED	CLOSED	CLOSED	CLOSED	CLOSED	CLOSED	CLOSED	CLOSED	CLOSED	CLOSED	CLOSED	CLOSED	CLOSED	CLOSED	CLOSED	CLOSED	CLOSED	CLOSED	CLOSED	CLOSED	CLOSED	CLOSED	CLOSED
Cv	9.17	20.9	N/A	N/A	0.53	0.53	0.53	1.51	1.51	1.51	1.51	2.58	1.48	1.42	2.39	2.39	3.63	1.45	1.54	3.65	1.45	4.37	4.37	1.33	3.3	4.32	
Max ΔP FT. HD	0.80	5.50	N/A	N/A	2.26	2.26	2.26	1.42	1.42	1.42	1.42	6.71	0.66	4.46	4.46	4.37	5.47	0.93	1.68	6.33	0.93	4.37	4.37	5.07	5.44	3.69	
BRANCH PIPE SIZE	1-1/4"	N/A	3/4"	3/4"	3/4"	3/4"	3/4"	3/4"	3/4"	3/4"	3/4"	3/4"	3/4"	3/4"	3/4"	3/4"	3/4"	3/4"	3/4"	3/4"	3/4"	3/4"	3/4"	3/4"	3/4"	1"	1"
VALVE CONFIGURATION	3-WAY	N/A	3-WAY	3-WAY	3-WAY	3-WAY	3-WAY	3-WAY	3-WAY	3-WAY	3-WAY	3-WAY	3-WAY	3-WAY	3-WAY	3-WAY	3-WAY	3-WAY	3-WAY	3-WAY	3-WAY	3-WAY	3-WAY	3-WAY	3-WAY	3-WAY	3-WAY
NORMAL TO COIL	OPEN	N/A	OPEN	OPEN	OPEN	OPEN	OPEN	OPEN	OPEN	OPEN	OPEN	OPEN	OPEN	OPEN	OPEN	OPEN	OPEN	OPEN	OPEN	OPEN	OPEN	OPEN	OPEN	OPEN	OPEN	OPEN	OPEN
Cv	34.00	N/A	1.11	0.90	1.11	1.11	1.11	1.04	1.04	1.04	1.04	2.51	1.15	2.45	2.45	2.48	2.48	2.36	1.15	1.15	2.36	1.15	2.48	2.48	1.03	4.48	1.82
Max ΔP FT. HD 8.22	2.1	N/A	1.36	1.01	0.29	0.29	0.29	0.29	0.23	0.23	0.23	1.34	0.27	0.24	0.24	0.94	0.94	2.08	0.27	0.27	2.08	0.27	0.94	0.94	3.43	1.45	9.83

AIR COOLED CHILLER																
MARK	DAIKIN MODEL NO.	AMB. °F	CAPACITY TONS	COMP. TYPE	NO. COMP.	NO. STAGES	EWT °F	LWT °F	CHILLER RATED CHW GPM	PUMP MAX CHW GPM	PUMP HEAD FT.	PUMP MOTOR HP	CHILLER MAX. PD FT. @ RATED FLOW	NO. COND. FANS	MAX UNIT KW	NOTES
CH-1	AGZ055E	95	55.8	SCROLL	4	4	55	45	132	156	65	5	14.0	4	79.6	1,2,3,4,5,6

NOTES:
1. BASIS OF DESIGN: DAIKIN
2. SINGLE POINT ELECTRICAL CONNECTION.
3. INTEGRAL DISCONNECT AND CIRCUIT PROTECTION.
4. INTEGRAL DUAL PUMPS PROVIDED AND PIPED COMPLETE WITH STRAINERS, TRIPLE DUTY VALVES, AND VARIABLE SPEED PUMP DRIVES.
5. INTEGRAL DUPLEX RECEPTACLE FOR MAINTENANCE.
6. 1 YR PARTS AND LABOR W/ 5 YEAR COMPRESSOR PARTS AND LABOR WARRENTY

PUMPS							
MARK	SERVICE	GPM	APPROX HEAD FT.	MOTOR HP	RPM	MIN EFF. %	NOTES
HWP-1	HOT WATER	92	65	5.0	1800	61.3%	B&G SERIES e-80 2X2X9.5C

NOTES:
1. NEMA 3R MOTOR ENCLOSURE RATING

HOT WATER BOILER							
MARK	HEATING INPUT MBH	GROSS OUTPUT MBH	EWT °F	LWT °F	HW GPM	NOTES	
B-1	1,000	850	160	180	89	PATTERSON-KELLY MODU-FIRE FORCED DRAFT BOILER MODEL N1000MD	

NOTES:
1. BOILER DESIGNED FOR EXTERIOR INSTALLATION.
2. LP GAS FIRED MODULATING CONDENSING BOILER WITH 5:1 TURN DOWN
3. 208V 1PH POWER
4. FACTORY INSTALLED PROBE TYPE LOW WATER CUT OFF
5. 30 PSIG PRESSURE RELIEF AND PRES-TEMP GAUGE

GRILLE SCHEDULE					
MARK	PRICE MODEL	SIZE	THROW	FINISH	NOTES.
(A)	8X8/MSSL/C6/B12	8X8	SIDEWALL	WHITE	
(B)	8X8/MSSG/8/B12	8X8	EXHAUST	WHITE	
(C)	8X8/630DAL/F/L/A/B12	8X8	EXHAUST	WHITE	W/ O.B.D
(D)	16X8/MSSG/8/B12	16X8	RETURN	WHITE	
(E)	8X8/MSSL/C7/8/B12	12X12	SIDEWALL	WHITE	
(F)	6X6/610Z/F/L/A/B12	6X6	SIDEWALL/EXH	WHITE	W/ O.B.D
(G)	12X6/LBPH25C/1000/VCS3/A/PA-42	12X6	FLOOR	DRK BRONZE	W/ O.B.D
(H)	12X2/LBPH25C/1000/VCS3/A/PA-42	12X2	FLOOR	DRK BRONZE	W/ O.B.D
(J)	10X6/610Z/F/L/A/B12	10X6	SIDEWALL/EXH	WHITE	W/ O.B.D
(K)	36X4/LBPH25C/1000/VCS3/A/PA-42	36X4	FLOOR	DRK BRONZE	W/ O.B.D
(L)	16X8/620DAL/F/S/A/B12	16X8	SIDEWALL	WHITE	W/ O.B.D
(M)	36X4/LBPH25C/1000/VCS3/A/PA-42	36X4	FLOOR	DRK BRONZE	W/ O.B.D
(N)	36X2/LBP15B/1000/DV/A/B-12	36X2	SIDEWALL SUPPLY	WHITE	
(O)	16X2.5/LBP15B/1000/DV/A/B-12	16X2.5	SIDEWALL SUPPLY	WHITE	W/ DIRECTIONAL VANES
(Q)	52X2.5/LBP15B/1000/A/B-12	52X2.5	SIDEWALL SUPPLY	WHITE	
(R)	60X3.5/LBP15B/1000/A/B-12	60X3.5	SIDEWALL SUPPLY	WHITE	
(S)	60X4/LBP15B/1000/A/B-12	60X4	SIDEWALL RETURN	WHITE	
(T)	52X3/LBP15B/1000/A/B-12	52X3	SIDEWALL RETURN	WHITE	
(U)	36X3/LBP15B/1000/A/B-12	36X3	SIDEWALL RETURN	WHITE	
(V)	16X3/LBP15B/1000/A/B-12	16X3	SIDEWALL RETURN	WHITE	
(W)	SDR100/2/2/ZZ/B12	NOTE 1	CEILING RETURN	WHITE	
(X)	60"/SDS50/4/2/ZZ/B12	NOTE 2	CEILING SUPPLY	WHITE	
(Y)	38X3/LBP15B/1000/A/B-12	38X3	SIDEWALL RETURN	WHITE	
(Z)	18X6/AMDE/1/3B/B12	18X6	CEILING SUPPLY	WHITE	
(AA)	9X6/AMDE/1/3A2/B12	9X6	CEILING SUPPLY	WHITE	
(BB)	30X60/60/A/S/A/B12	30X60	SOFFIT	WHITE	
(CC)	6X6/AMDE/1/1S/B12	6X6	CEILING SUPPLY	WHITE	
(DD)	10X10/630/F/L/A/B12	10X10	EXHAUST	WHITE	
(EE)	38X2/LBP15B/1000/A/B-12	36X2	SIDEWALL SUPPLY	WHITE	

NOTES:
1. CONTINUOUS SLOT GRILLE WITH ACTIVE SECTIONS AS INDICATED ON THE PLANS. PROVIDE NECESSARY END CAPS, ALIGNMENT STRIPS AND METAL BLANK-OFFS. FIELD MEASURE AND CUT TO ENSURE PRECISE FIT. PROVIDE INSULATED SLOPED SHOULDER PLENUMS WITH DUCT CONNECTION NOT SMALLER THAN INDICATED FLEX DIAMETER AND TRANSITION TO INDICATED FLEX DUCT SIZES.
2. 60" 4-SLOT GRILLE. PROVIDE NECESSARY END CAPS. PROVIDE INSULATED SLOPED SHOULDER PLENUMS WITH DUCT CONNECTION NOT SMALLER THAN INDICATED FLEX DIAMETER AND TRANSITION TO INDICATED FLEX DUCT SIZES. ADJUST THE TWO EXTERIOR SLOTS TO THROW STRAIGHT DOWN AND THE TWO INTERIOR SLOTS TO THROW TOWARD THE INTERIOR OF THE SPACE. RESULTING THROW CONFLICT IS INTENTIONAL.

AIR HANDLING UNITS																			
MARK	DESIGN SUPPLY CFM	FAN DATA				COOLING COIL DATA						HEATING COIL DATA						NOTES	
		O.A. CFM	ESP IN. WG	MOTOR BHP	TOTAL COOLING MBH	SENSIBLE COOLING MBH	Edb	Ewb	Ldb	Lwb	CHW GPM	MAX. PD FT.	MAX. AIR PD IN.	HEATING OUTPUT MBH	AIR ΔT°F	HW GPM	MAX. PD FT.		MAX. AIR PD IN.
AHU-B1	6400	1745	1.25	5.67	45.5	36.3	60	57	55	54	8.2	0.8	0.67	246.9	55.6	49.3	2.1	0.35	1,2

NOTES:
1. PROVIDE WITH MERV 8 AIR FILTERS.
2. 3-WAY VALVES FOR COILS. NORMALLY OPEN TO BY-PASS FOR COOLING, NORMALLY CLOSED TO BY-PASS FOR HEATING.

ENERGY RECOVERY UNIT																								
MARK	SUPPLY FAN DATA			EXHAUST FAN DATA			ENTHALPY WHEEL DATA						COOLING COIL DATA						NOTES					
	O.A. CFM	ESP IN. WG	MOTOR BHP	EXHAUST CFM	ESP IN. WG	MOTOR BHP	O.A.			EXHAUST AIR			TOTAL COOLING EFFECT.	SENSIBLE COOLING EFFECT.	Edb	Ewb	Ldb	Lwb		CHW GPM	MAX. PD FT.	MAX. AIR PD IN.		
ERU-1	4275	1.0	4.9	3090	1.0	2.7	96	77	83.6	70.8	75	65	92.1	75	79.12%	83.19%	84	72	55	55	48.9	5.5	0.71	1,2

NOTES:
1. BOTH AIR STREAMS TO BE PROVIDED WITH MERV 8 AND MERV 13 AIR FILTERS.
2. 3-WAY VALVE FOR COOLING COIL. NORMALLY OPEN TO BY-PASS.

